# Chapter 2 PROGRESS ON THE WORLD TRADE CENTER INVESTIGATION

#### 2.1 STATUS OF DATA COLLECTION EFFORTS

The National Institute of Standards and Technology (NIST) is basing its review, analysis, modeling, and testing work for the World Trade Center (WTC) Investigation on a solid foundation of technical evidence. This requires access to critical data such as building documents, videographic and photographic records, emergency response records, and oral histories, in addition to the samples of steel that have been recovered.

NIST has received considerable cooperation and large volumes of information from a variety of organizations and agencies representing the building designers, owners, leaseholders, suppliers, tenants, first responders, contractors, insurers, news media, survivors, and families of victims. In addition, NIST has received and is grateful for cooperation from The National Commission on Terrorist Attacks Upon the United States (9-11 Commission). The documents and other information relate to the design, construction, operation, inspection, maintenance, repair, alterations, emergency response, and evacuation of the WTC complex.

Local authorities providing information include the Port Authority of New York and New Jersey (PANYNJ or Port Authority) and its consultants and contractors; the New York City Fire Department (FDNY); the New York City Police Department (NYPD); the New York City (NYC) Law Department; the NYC Department of Design and Construction; the NYC Department of Buildings; and the NYC Office of Emergency Management. In addition, the Occupational Safety and Health Administration provided correspondence sent to it regarding the evacuation experience of WTC occupants on September 11, 2001.

NIST also has received information from Silverstein Properties and its consultants and contractors; the group of companies that insured the WTC towers and its technical experts; Nippon Steel; Laclede Steel; U.S. Mineral Products Co. and Isolatek International; Morse Zehntner Associates; W.R. Grace & Co.; Citigroup, formerly Salomon Smith Barney; United Airlines; American Airlines; and Boeing. NIST also received information on floor plans, furnishings, and contents from tenants of all three buildings.

The information from Silverstein and the insurance companies includes the large body of technical work completed by both parties as part of the insurance litigation involving the WTC towers, such as reports on the structural collapse, fire spread and severity, and wind tunnel test results for the WTC towers. In addition, technical experts for both parties independently provided extensive briefings to the WTC investigation team and discussed the tenability environment and the evacuation procedures in the buildings.

**NIST has received all of the essential information it needs for the WTC investigation.** That information includes NYC 9-1-1 tapes, the transcripts of approximately 500 interviews of employees of the FDNY who were involved in WTC emergency response activities, and supporting documents for McKinsey & Company's FDNY study.

The following is the list of documentary information received or inspected by NIST.

## December 2002

- The original design drawings (structural, architectural, mechanical, electrical, plumbing) and the original fabrication and construction drawings for the WTC towers
- Tenant alteration application reports, including drawings and specifications, for the WTC towers and WTC 7, and associated construction audit reports
- Tenant design standards manuals for structural; architectural; heating, ventilating, and airconditioning (HVAC); fire protection; plumbing; electrical; fire alarm; and construction review
- Emergency evacuation procedures manuals, including fire safety guide
- Operations manuals for the fire protection system, including sprinklers, standpipes, alarm system and communication protocols, and water and power supply
- Operations manuals for the HVAC systems
- Reports on facility condition surveys and structural integrity inspections for the WTC towers and WTC 7
- Recent inspection and maintenance reports for the elevators and escalators in the WTC towers; elevator numbering system
- Reports on pre-design tests of structural components, including dampers for the WTC towers
- Reports on wind tunnel tests of the WTC towers and wind speed measurements near the WTC site
- Reports on the 1993 bombing damage assessment and repairs, and documentation of changes made to the evacuation system after 1993
- Documents related to the location, approval, and inspection of fuel tanks in WTC 7
- Documents related to fire rating and fireproofing of structural steel members in the WTC towers
- Documents related to PANYNJ building and fire code requirements and practices
- Correspondence sent to the Occupational Safety and Health Administration regarding the evacuation experience of WTC occupants on September 11, 2001
- Documents related to the lease of the WTC towers by Silverstein Properties
- Reports prepared by McKinsey & Company for FDNY and NYPD

- Basic FDNY dispatch data, including time of dispatch and unit identification
- Firefighter fatality and injury data from FDNY

## May 2003

- More than 1,000 hours of recordings made by PANYNJ on September 11, 2001 (from 0705 through 1900 hours) of telephone calls, as well as police, fire, operations, maintenance, security, and other radio transmissions from four distinct locations
- Personal injury data from FDNY and Port Authority of New York and New Jersey Police Department (PAPD)
- Handwritten notes on the events of September 11, 2001, by PAPD staff
- Emergency responder fatality data for FDNY, NYPD, and PAPD
- WTC list of tenants with contact information from PANYNJ and Silverstein
- WTC list of occupants issued security badges by PANYNJ
- Report on WTC smoke management system by Hughes Associates, Inc.
- Phase I and final reports on fire engineering of WTC steelwork by Buro Happold
- Transcripts of depositions by two PANYNJ staff in the WTC insurance litigation
- Documents, videos, and photographs related to the fireproofing of the WTC tower structures
- WTC floor plan for the fire alarm system and drawings of WTC subgrade plumbing and city water main
- Information regarding building contents such as partitions and furnishings from a key WTC tower tenant, to characterize the types of combustibles and estimates of the mass loading in the region of the fires
- FDNY WTC incident summary, September 20, 2001
- FDNY reports on the fire history of WTC 1, 2, and 7 from 1970 to 2001
- FDNY reports related to inspections of WTC 1, 2, and 7 from 1999 to 2001
- FDNY policies and practices on operations specific to the WTC buildings and on accountability of firefighters at incidents
- FDNY information on dispatched units, apparatus, command posts, and staging areas
- FDNY information on number of command and company officers and firefighters operating in and around WTC 1, 2, and 7 with number of surviving personnel

 Detailed briefing on the NYPD communications system, including 9-1-1 system and radio networks

## August 2003

- Design and structural calculations from Leslie E. Robertson Associates (LERA) for the WTC towers, including TV antenna, beams, and beam girders, as well as wind analysis and calculations
- Correspondence from LERA during the time of construction
- Laclede floor truss shop drawings (1,364 sheets) and other documents on steel and joints
- Information on steel from Nippon
- List of WTC drawings in possession of Yamasaki and Associates
- Information on the flammable contents of the American Airlines B-767 aircraft
- Information regarding building contents and floor layouts from some WTC tower and WTC 7 tenants
- Mechanical and electrical specifications for WTC 7
- Asbestos litigation documents from PANYNJ
- Underwriters' Laboratories, Inc. (UL) test reports regarding spray-on fireproofing from supplier (Isolatek)
- Correspondence on the selection of WR Grace fireproofing products, test data, and UL design listings (WR Grace)
- Data on the WTC internal radio system and FDNY radio repeater from PANYNJ
- Some FDNY training practices for operations in high-rise buildings
- Global positioning system coordinates and map where human remains and equipment were located from FDNY
- Information on FDNY personnel killed on September 11, 2001, and map of fire and Emergency Management Services Command Post Locations
- NYPD internal communications concerning the terrorist attacks on WTC (43 cassette tapes)
- Disaster Response Plan, Patrol Guide Procedures, and other guides and manuals from NYPD, including the Unusual Occurrence Report on the 1993 WTC bombing
- A large portion of NYPD and FDNY extensive photographic and videographic collection

- Updated badge list of WTC occupants maintained by PANYNJ
- WTC fire safety and PA/FDNY WTC training videos and pre-September 11, 2001 WTC photographs

#### September 2003

- Information on the flammable contents of the United Airlines B-767 aircraft
- Documents from PANYNJ on accessibility for disabled persons, active fire protection systems, and adoption of revisions to NYC Building Code
- Elevator and escalator contract information from PANYNJ
- Status of changes to WTC towers (March 1973) from PANYNJ
- Transcripts from September 11 PAPD audiotapes, police reports, and PAPD special awards ceremony documents for September 11, 2001
- Additional documents from PANYNJ on asbestos litigation

#### October 2003

- Supporting documents for McKinsey & Company's FDNY and NYPD studies
- Review of UL test reports regarding spray-on fireproofing from supplier (W.R. Grace)
- Information from Boeing on flammable contents of aircraft that contributed to fires

#### May 2004

- Review of NYC 9-1-1 tapes and logs, transcripts of about 500 first responder interviews with employees of the FDNY who were involved in WTC emergency response activities
- General description of WTC building systems and capital program
- WTC documents presented as exhibits in asbestos litigation
- Additional documents on WTC maintenance services, accessibility, elevators, code compliance, fire rating, fire detection system, fire alarm system, etc.
- Photographs of WTC 7 construction project
- Architectural and HVAC drawings for WTC 7, including modifications
- Well in excess of 6,000 photographs representing more than 185 professional and amateur photographers. Organizations that have provided materials include FDNY, NYPD, Associated Press, Corbis, Reuters, *The New York Times*, *The New York Daily News*, and the

*Star Ledger*. Many organizations have provided both published and unpublished photographs.

 In excess of 150 hours of videotapes from news media (NBC, CBS, ABC, CNN, and local New York stations WABC, WCBS, WNBC, WPIX, WNYW, and New York One), FDNY, NYPD, and more than 20 individuals. In many cases, the videos provide not only broadcast material (known as air checks), but also material that was recorded but not broadcast (known as outtakes).

The few NIST requests for materials that are lost, currently pending, or not yet located include:

- Original contract specifications for WTC towers (lost in the collapse of the buildings)
- Construction and maintenance logs for WTC 1, 2, and 7 (lost in the collapse of the buildings)
- Calculations and analyses that supported the original aircraft impact studies (lost in the collapse of the buildings)
- Descriptions of partitions and furnishings in most of the tenant spaces of WTC 2 and WTC 7 in the fire and impact zones
- Shop drawings showing connection details of WTC 7

NIST is making efforts to assemble this information from various sources because much of it was lost when the buildings collapsed. NIST continues to pursue other materials that can further clarify some aspects of the Investigation.

## 2.2 ANALYSIS OF BUILDING AND FIRE CODES AND PRACTICES (PROJECT 1)

## 2.2.1 Project Objective

One of the four primary objectives of the NIST Investigation of the WTC disaster is to determine the procedures and practices that were used in the design, construction, operation, and maintenance of the WTC towers and WTC 7. A key focus is on acceptance procedures and practices for innovative systems, technologies, and materials, and for variances from requirements of building and fire code provisions. This documentation of historical information is expected to be of value to the professional community in identifying and adopting changes to procedures and practices that may be warranted.

For most buildings constructed in the United States, building codes adopted by local jurisdictions establish minimum requirements for design and construction. However, because PANYNJ is an interstate agency, its construction projects are not required to comply with any local or national model building code. Thus, to determine the criteria, procedures, and practices that were used in the design, construction, operation, and maintenance of WTC 1, 2, and 7, Project 1, Analysis of Building and Fire Codes and Practices, has the following objectives:

• Document the requirements that governed the design and construction of WTC 1, 2, and 7

- Document any differences between the Port Authority requirements used for design and the then current building code requirements of other jurisdictions and the appropriate model building code
- Document the procedures used by the Port Authority to accept new and innovative design features that deviated from the Port Authority building design requirements
- Document the procedures used to accept new technologies and materials that were not recognized by then-current standards
- Document passive and active fire safety, emergency access and egress provisions that were incorporated in the original design and subsequent modifications during occupancy
- Document major modifications made to structural, fire protection, and egress systems of WTC 1, 2, and 7
- Document the inspection and maintenance procedures used for WTC 1, 2, and 7.

## 2.2.2 Project Approach

The design and construction documents of the WTC buildings that were kept centrally at the Port Authority office in WTC 1 were destroyed when the tower collapsed. Thus, existing copies of design and construction documents of WTC 1, 2, and 7 had to be assembled from various sources that were associated with these projects. Documents were obtained principally from:

- The Port Authority, and
- Architectural and engineering firms who designed and inspected the WTC buildings.

In addition, information was obtained from others who were associated with WTC 1, 2, and 7 construction projects.

The information collected will enable the NIST investigators to accomplish the five tasks of Project 1:

- Task 1. Document the design and construction of structural systems to determine:
  - Provisions used to design and construct the buildings. This will include the Port
    Authority building design and construction requirements, the building code used,
    standards referenced, and Port Authority policies and agreements with the NYC
    Department of Buildings regarding building code requirements.
  - Tests performed to support the design, such as wind tunnel tests and tests of structural assemblies.
  - Criteria used to proportion structural members and other components of the buildings including structural connections.

- Innovative systems, technologies, and materials that were used, and the acceptance procedures used by the Port Authority.
- Variances granted by the Port Authority, including the justification for those variances.
- Special fabrication and inspection requirements.
- Inspection protocols used during construction.
- Technical problems that occurred during construction of the buildings and their resolution.
- Task 2. Document the design and construction of the fire protection and egress systems to determine:
  - Provisions used to design and construct the fire protection (passive and active) and egress systems of the buildings. This will include the Port Authority building and fire regulatory requirements, the building and fire code used, and standards referenced.
  - Building regulations adopted after the issuance of the certificates of occupancy, or equivalent, that were applied to the buildings through retroactivity (including any provisions of NYC Local Laws), and any permits issued or special inspections required resulting from the installation of special hazards or equipment in the buildings.
- Task 3. Document the fuel system for emergency power in WTC 7 to determine:
  - Locations of emergency power generating systems;
  - Size and locations of the fuel storage tanks and distribution systems;
  - Specific fire protection systems used for the fuel storage and distribution systems;
  - Normal and emergency operating procedures; and
  - Maintenance history.
- Task 4. Compare building regulatory and code requirements to document:
  - Port Authority building regulatory requirements.
  - Differences among the Port Authority building regulatory requirements and the thencurrent NYC, New York State, Chicago, and Building Officials Conference of America (now known as the Building Officials and Code Administrators [BOCA]) building code provisions.
  - Differences between the Port Authority building regulatory requirements and the current (2001) NYC Building Code provisions.

- Evolution of the life safety provisions in the NYC Building Code since the design of WTC 1 and WTC 2.
- Task 5. Document maintenance of and modifications to the structural, fire protection, and egress systems to determine:
  - Guidelines used by the Port Authority for inspection, repair, and modifications to structural, fire protection, and egress systems.
  - Structural integrity inspection programs during the occupancy of the buildings.
  - Any significant modifications and/or repairs of the original structural framing system by the owner or tenants during original construction and occupancy.
  - Any repairs and modifications made to the passive and active fire protection systems from initial occupancy to September 11, 2001.

#### 2.2.3 Status of Tasks

Except for the task of comparing building regulatory and code requirements (Task 4), the tasks depend upon the availability of design, construction, and maintenance documentation related to WTC 1, 2, and 7. Efforts by NIST to obtain needed documents are described briefly, and the current status of each of the five tasks is stated below

Sections 2.2.4 and 2.2.5 present salient points related to Tasks 1 and 2, particularly how changes in NYC Building Code provisions from the 1938 edition to the 1968 edition, and subsequent promulgation of NYC Local Laws, affected the design, construction and maintenance of WTC 1, 2, and 7. Section 2.2.6 describes the fuel system that powered the emergency generators in WTC 7 (Task 3). Comparison of the requirements of several building codes (Task 4) pertaining to structural and fire safety is presented in Appendix A, Interim Report on the Analysis of Building and Fire Codes and Practices, of this report. Task 5, which deals with maintenance and modifications to the structural, fire protection, and egress systems of WTC 1, 2 and 7, is near completion.

## **Collection of Design and Construction Data**

NIST requested that the Port Authority and the design and construction firms for WTC 1, 2, and 7 provide design, construction, and maintenance documents. NIST obtained a considerable amount of information (design drawings, shop drawings, specifications, project correspondence, and inspection reports) related to WTC 1 and WTC 2 from the structural engineers who were involved in the original design and subsequent modifications to the towers. The Port Authority provided construction related files for WTC 1, 2, and 7, mostly pertaining to tenant alteration projects, wherein tenants modified parts of the buildings to meet their needs. No document was obtained from the general contractor of WTC 1, 2, and 7. The general contractor retains construction documents for about 7 years. As a result, few records are available related to changes to the structural and fire safety systems that were made during construction of these buildings. However, documents obtained from the structural engineer included revisions to structural modifications for tenant renovations.

It should be pointed out that there is no mandated requirement by NYC for design and construction firms to retain their documents for a specific duration. Currently, no municipalities in the United States have document retention policies that require design and construction firms to retain their documents.

Collected documents have been examined by NIST, and pertinent documents have been organized into a searchable database. Using keywords, the user of the database can retrieve relevant documents. NIST has engaged a contractor to assist in reviewing the vast amount of documentation that has been collected.

## **Task Status and Report Preparation**

Under NIST guidance and direction, a team of NIST contractors, led by Rolf Jensen and Associates, Inc., has made an in-depth review of the relevant documents and is in the process of preparing draft reports that address the Project 1 tasks. Independent examination of documents by NIST engineers together with the contractor's reports will be the basis for the final report of this project. Table 2–1 indicates the status of each of the tasks.

Table 2–1. Status of Project 1 tasks.

Task	Status				
1	Documented code provisions used to design and construct WTC 1, 2 and 7. Documented criteria used to design WTC 1 and WTC 2. Contractor submitted final draft report to NIST.				
2	Documented code provisions used to design and construct the passive and active fire protection systems for WTC 1, 2, and 7. Documented adoption of Local Laws that modified and/or amended the fire safety provisions of the 1968 NYC Building Code.  Contractor submitted second draft report to NIST.				
3	Documented all emergency power generating systems and the size and locations of the fuel storage tanks and distribution system in WTC 7.  Contractor submitted final draft report to NIST.				
4	Documented line-by-line comparison of structural and life safety provisions of the 1968 NYC Building Code vs. three other contemporaneous building codes and the 2001 NYC Building Code.  Contractor submitted final draft report to NIST.				
5	Documented repairs, modifications to the structural and fire protection systems, and emergency access and egress systems.  Contractor submitted final draft to NIST.				

## 2.2.4 Building Codes

As discussed in Appendix A, the Port Authority adopted the 1968 NYC Building Code (NYCBC 1968) for the final design of the WTC buildings. Therefore, this code served as the basis for the code comparison. NIST examined the structural and fire safety provisions in several contemporaneous codes, including the 1964 New York State Building Construction Code (NYSBC 1964), the 1965 BOCA model building code (Basic Building Code), the 1967 Municipal Code of Chicago (MCC 1967), and the 1966 National Fire Protection Association (NFPA) 101 Life Safety Code (NFPA 1966) egress requirements. A comparison was also made between the 1968 NYC Building Code and the current (2001) NYC Building

Code. The current NYC Building Code (NYCBC 2001) is basically the document adopted in 1968 with modifications made over the years by adoption of Local Laws and rules.

Because fire protection and fire safety provisions are of major importance to this Investigation, this section provides background information on building codes, focusing on matters related to fire protection. Appendix A provides additional background information and provides a summary of the code comparison.

## **Code Provisions on Fire Safety**

The fire safety provisions in building codes can be confusing to those who are not familiar with the code provisions that have evolved over the past century. The following provides basic concepts related to fire protection and fire safety.

#### Fire Rating

This is a time expressed in hours or minutes. It represents fire resistance assigned to a building element on the basis of a test. Fire rating is the time that a test assembly is able to withstand the furnace temperature exposure specified in American Society for Testing and Materials (ASTM) E 119 (ASTM 2003) without exceeding one of the "failure conditions." Thus, a fire rating of 2 h for a structural member indicates that when the member was tested in accordance with ASTM E 119, it performed successfully for at least 2 h. It is not necessary to conduct a test for all materials to be used in a building if data are available from past standard tests showing acceptable performance, and the same materials and application methods will be used. The fire rating of a member or assembly does not indicate for how long a similar member or assembly in the building would perform under a real fire because the actual fire exposure and structural configuration are never the same as during the ASTM E 119 test.

#### Occupancy Group

Buildings and spaces are classified according to how the buildings and spaces will be used. The concept of "occupancy group" is used to define different types of occupancy or use such as storage, industrial buildings, general assembly, business, and so forth. A given occupancy group is associated with a different level of fire risk. Factors such as amount of combustible material, ignition sources, and characteristics of the occupants are considered in developing these groupings. In some codes, such as the 1968 NYC Building Code, occupancy groups are listed in a hierarchal sequence (highest to lowest hazard) and assigned an overall "fire index" rating in hours. For example, "high hazard" occupancy is assigned a fire index of 4 h, while "business" occupancy is assigned a fire index of 2 h.

#### Construction Classification

The nature of the materials used in constructing exterior walls and interior building elements define the construction type. In general, building codes characterize construction materials as "combustible" and "noncombustible" materials. For example, the 1968 NYC Building Code uses the designations "Group I" and "Group II" for noncombustible and combustible construction materials, respectively. Other codes, however, also consider whether these types of materials are used in exterior walls, or interior elements, or both. For example, International Building Code (IBC) 2000 (ICC 2000) lists Type I through Type V. These types, or groups, are further divided into different subclasses that are designated with letters, such

as Class IA, Class IB, Class IIA, Class IIB, or in some codes as Type IA, Type IB, Type IIA, Type IIIA, and so forth. Building codes typically include tables that specify fire ratings for different structural elements (columns, walls, beams) and for different construction classifications (Type IA, Type IB, and so forth).

#### Height and Area Limits

Tall buildings and buildings with large floor areas pose greater risks in the event of fire. Building codes, therefore, place limitations on the heights and floor areas of buildings based on the construction classification, the occupancy group, and whether or not the building has sprinklers.

#### **Partitions**

Partitions, in general, are walls that provide separations between spaces within the story of a building. Partitions may or may not require minimum fire ratings, depending on the spaces being separated. In general, three types of partitions require fire ratings:

- Walls that provide separations between different occupancy groups
- Walls that provide separations between tenants (often called demising partitions)
- Walls that separate large floor areas into smaller compartments

Buildings codes specify different minimum fire ratings based on the type of partition and the types of occupancies in the spaces being separated.

#### Variances

All building codes make allowances for obtaining approval of materials and methods not strictly in compliance with code provisions, but which are judged to be equivalent. Normally, the regulatory authority makes this equivalence determination during the plan approval process, and a variance is issued. Compliance with building code provisions is verified by controlled inspections by building (and fire) inspectors at specified points in the construction process using sets of approved plans showing all such variances.

## **Evolution of Fire Safety Provisions in Model Building Codes**

Model building codes are documents prepared by qualified nongovernmental organizations. When adopted by local jurisdictions, the code provisions become law. The following provides a short review of the evolution of provisions in model codes related to types of construction and fire resistance requirements of structural elements.<sup>6</sup>

The 1927 edition of the Uniform Building Code (ICBO 1928) placed office occupancies in Group F Division 1 and allowed only Type 1 construction for such buildings. This required a 4 h fire rating for

-

This historical summary was provided by Joseph Messersmith of the Portland Cement Association with a letter of July 31, 2002. See also Messersmith (2002).

columns, beams, and girders and a 3 h rating for floors for buildings (steel and reinforced concrete) over eight stories or 85 ft in height.

The 1934 (5th) edition of the National Building Code (NBFU 1934) required business buildings over 75 ft in height to be "fireproof" construction, defined as having a 4 h fire rating for bearing walls, firewalls, party walls, piers and columns, and a 3 h rating for other walls, girders, beams, and floors.

The 1946-1947 edition of the Southern Standard Building Code (SBCC 1946) required Type 1 construction for business occupancies over 80 ft in height. Type 1 was defined as a 4 h fire rating for columns, bearing walls, trusses or girders supporting masonry or bearing walls, columns or girders, and beams, and a 2 1/2 h rating for floors. There is, however, a note under Type 2 construction that allows residential and business occupancies of unlimited height with a rating of 3 h for columns and a rating of at least 2 h for other structural members including floors.

The 1950 Basic Building Code (BOCA 1950) permits Group E business occupancies of unlimited height to be Type 1A or 1B. Type 1A requires a 4 h fire rating for bearing walls and for columns supporting more than one floor, and 3 h rating for floors including beams. Type 1B reduces those to 3 h and 2 h, respectively. Because this is the model code used in the Northeastern United States, this may have provided the basis for the changes from the 1938 to the 1968 NYC Building Code (see next section). However, because records of technical substantiations for code changes were not kept in this era, conclusive evidence does not exist.

## **Evolution of the NYC Building Code**

Historically, NYC has developed and promulgated its own building code, in contrast to most jurisdictions that adopt (locally modified) versions of one of the model building codes. At the time the WTC project was begun (early 1960s), the 1938 NYC Building Code, which was first adopted January 1, 1938, was in effect and enforced throughout the five boroughs.

In the late 1950s, it was noted that "great changes have occurred in all facets of the building industry" and that "As a result of these developments, and the failure in many instances, of the Code to keep pace, there had been a growing dissatisfaction with it" (Schaffner 1964). Thus in 1960, the Building Commissioner requested the New York Building Congress to form a working committee to study the problem. The committee recommended that the Code should not be rewritten by a group of volunteers and that a local educational institution should conduct a study to develop an approach to solve the problem. The Polytechnic Institute of Brooklyn conducted the study, and in July 1961, the Institute made the following recommendations (Schaffner 1964):

- 1. The NYC Building Code be completely rewritten. The new Code should provide for frequent periodic revision through a committee or board appointed solely for this purpose.
- 2. The new Code be a combination of performance and specification types with heavy emphasis on performance, wherever possible, and with liberal reference to accepted national standards.
- 3. The BOCA Basic Building Code be used as a guide for the development of the NYC Building Code.

4. The Code be rewritten by a private professional group such as an engineering company, architectural firm, educational institution, or any combination of the three. Those rewriting the Code should work closely with the NYC Building Department. They should be supported, for review purposes, by volunteer committees composed of representatives of professional, trade, and industry associations."

In April 1962, NYC signed an agreement with the Polytechnic Institute of Brooklyn for the writing of a new Code to be completed in 3 years. The first draft was completed in 1964. A public relations document highlighted the "major advantages to be gained from recommendations in the proposed new Building Code" (Bell and Stanton 1964). One of these related to the "area and height limitations," and it was stated that:

Area and height limitations will be liberalized and present unrealistically high construction requirements for fire protection in structures of low combustible content such as auditorium, halls, schools, institutions and residences will be significantly reduced and considerable economy will result.

On December 6, 1968, Local Law 76 repealed the 1938 code and replaced it with the 1968 code, which itself was subsequently amended by Local Laws. As is the general custom with changes to building codes, the new provisions generally are not applied to existing buildings (those approved under the prior code) provided they do not represent a danger to public safety and welfare.

There were 79 Local Laws adopted between 1969 and 2002 that modified the 1968 code. Of particular importance with regard to fire protection and life safety are Local Law 5, adopted in 1973, and Local Law 16, adopted in 1984. Local Law 5, among other things, added requirements on compartmentation of large floor areas, and Local Law 16 added requirements for sprinklers in high-rise buildings (greater than 100 ft). Local Law 5 is particularly significant because its provisions, which are reviewed in a subsequent section, applied retroactively to existing office buildings. Local Law 84, which was passed in 1979, revised the compliance dates of Local Law 5 so that full compliance was required by February 7, 1988.

As discussed in Appendix A, the 1968 NYC Building Code contained a number of provisions not addressed in the other codes of the time, but which were added to these other codes at later times.

#### Selection of Construction Type for WTC Towers

The 1938 NYC Building Code recognized one construction type for buildings of unlimited height and area, namely Class 1—Fireproof Structures, which required a 4 h fire rating for columns and a 3 h rating for floors. In the 1968 code, Group I (Noncombustible) construction was subdivided into "Class 1A—4-hr protected" and "Class 1B—3-hr protected" construction. Class 1A specifies similar protection as the previous Class 1, and Class 1B specifies a 3 h rating for columns and girders supporting more than one floor and a 2 h rating for floors including beams. Both Class 1A and Class 1B construction permit unlimited height and area for unsprinklered business occupancy.

If a building qualifies for more than one construction classification, such as Class 1A or Class 1B, codes are silent on which classification should be used. In such situations, the classification selected for construction is at the discretion of the owner/architect. To date, no contemporaneous documentation has

been found that provides the rationale for the decision to select Class 1B for the WTC towers. This decision, however, appears to have been made by the architect-of-record on the basis of economics. In a 1987 memorandum on the subject of fire rating of the WTC buildings, the following statement was included (Feld 1987):

For office buildings there is <u>no</u> economic advantage in using Class 1A Construction, and ER&S [architect-of-record] used Class 1B Construction for the WTC Towers and Plaza Buildings which are Occupancy Group "E" (Business) with a fire index of 2 hours.

An interoffice memorandum between staff of the general contractor written in 1969 is the only contemporaneous document found to date that refers to the classification of the WTC towers (Bracco 1969). The following statement is included in that memorandum:

The WTC towers would be classified, by our interpretation of the code, as occupancy Group E, Business; Construction Group 1, Noncombustible; and Construction Classification 1-B, (since there are no area or height limitations applicable).

## 2.2.5 The 1968 New York City Building Code

#### **Applicability to Port Authority Properties**

Established in 1921, the Port Authority is a self-supporting, public interstate agency and is not subject to the local laws of jurisdictions where its properties are constructed. This means that for the construction of the WTC buildings, the Port Authority was not bound by the NYC Building Code or any regulations requiring inspection or approval of the building construction or operation. The Port Authority could establish its own requirements, conduct its own inspections, and enforce its own rules without independent oversight.

According to a joint report written by the Fire Commissioner and Commissioner of Buildings on March 15, 1993 (after the 1993 bombing), in 1975 the NYC Council submitted a resolution to the New York State Legislature to require the Port Authority to comply with the NYC Building Code when building within the City (Rivera and Rinaldi 1993). The 1993 report includes the following statements with respect to jurisdiction over the WTC complex:

After several major fires in the 1970s, the Fire Department in 1975 testified at the City Council for the need to have jurisdiction over this complex as well as other buildings owned by public benefit corporations, again particularly for Local Law 5 compliance. As a result, the City Council forwarded a Resolution dated August 29, 1975, to the State legislature. ... Proposed legislation which would have granted City agencies jurisdiction was introduced in the State legislature over the years; the State has not enacted such legislation.

It appears that there was friction between the FDNY and the Port Authority as evidenced by the following statements in the same joint report (Rivera and Rinaldi 1993):

Prior to the February 26, 1993, explosion, the Fire Department acted pursuant to the joint protocol for inspectional activity at the WTC which was signed in 1986. The Port Authority's policy was to voluntarily cooperate with the Fire Department 'to the fullest extent practicable.' Fire Department representatives met continually with Port Authority officials to discuss problems with the WTC's emergency procedures and fire safety equipment. Generally, the Port Authority was cooperative and verbally informed the Fire Department that it was their intent to fully comply with Local Law 5. However, since its compliance with fire code requirements was dependent upon economic and design feasibility, the PA agreed to comply with selected provisions of the code, but has not fully done so. Moreover, it was difficult for the Fire Department to monitor code compliance by the WTC because the WTC consistently asserted its legal exemption from local law. Fire officials relied on persuasion and negotiation to gain compliance. The extent of these negotiations is reflected in the voluminous WTC files maintained at the Fire Department. Code compliance at the WTC has been dealt with by every Fire Commissioner and Chief of the Department over the last twenty-five years.

It was not until 1993 that a formal agreement was reached between the Port Authority and the NYC Department of Buildings with regard to code conformance for Port Authority buildings constructed in NYC (PANYNJ and NYCDOB 1993). The introduction of the memorandum of understanding contained the following statements:

While the facilities of the Port Authority, an agency of the States of New York and New Jersey, are not technically subject to the requirements of local building codes, the long-standing policy of the Port Authority has been to assure that its facilities meet and, where appropriate, exceed Code requirements.

The purpose of this Memorandum is not only to restate that longstanding policy as part of an understanding with the City but to provide specific commitments to the Department, as the agency of the City responsible for assuring compliance with the Code, regarding procedures to be undertaken by the Port Authority for any Project at its facilities in the City to assure that the buildings owned or operated by the Port Authority within the City are in conformance with the Building Standards contained in the Code.

Some salient points included in this agreement are:

- Each project would be reviewed and examined for compliance with the Code;
- All plans would be prepared, sealed, and reviewed by New York State licensed professional engineers or architects; and

• The Port Authority engineer or architect approving the plans would be licensed in the State of New York and would not have assisted in the preparation of the plans.

This agreement was enhanced in 1995 by the approval of a supplement to the 1993 memorandum of understanding (PANYNJ and NYCDOB 1995). The supplement added that:

• The person or firm performing the review and certification of plans for WTC tenants should not be the same person or firm providing certification that the project had been constructed in accordance with the plans and specifications.

In 1993, the Port Authority entered also into an agreement with the FDNY related to fire safety inspections (PANYNJ and FDNY 1993). The introduction to the memorandum of understanding contains the following statements:

On April 15, 1993, the Port Authority, in order to maintain and enhance the safety of Port Authority facilities, adopted a policy providing for the implementation of fire safety recommendations made by local government fire departments after a fire safety inspection of a Port Authority facility and for the prior review by local fire safety agencies of fire safety systems to be introduced or added to a facility.

The purpose of this Memorandum of Understanding is to reiterate the Port Authority's commitment to this policy and to set forth certain procedures to facilitate the implementation of this policy for buildings at Port Authority facilities located in New York City.

The agreement recognized the right of the FDNY to conduct fire safety inspections of Port Authority properties in NYC and provided guidelines related to corrective actions.

## Port Authority's Transition from the 1938 to the 1968 Code

As discussed in Appendix A, in 1963 the Port Authority instructed the designers of the WTC to follow the then current 1938 NYC Building Code. During this time, the code was in the process of being revised (as noted above), and in 1965, the Port Authority directed its designers to adopt the draft version of the new code for their final designs. Some of the advantages of the new draft code were noted to be the following (Levy 1965):

- Fire towers<sup>7</sup> could be eliminated;
- Provisions for exit stairs were more "lenient;" and
- Criteria for partition weights were more "realistic."

It was not certain whether all the changes being proposed to the 1938 code would be incorporated into the final version of the new code. Thus in 1966, the Chief Engineer of the Port Authority suggested that the

<sup>&</sup>lt;sup>7</sup> A "fire tower" is a stair tower enclosed within a 4 h fire rated shaft that is entered through a naturally ventilated vestibule. The 1938 Code stipulated that one of the required exits in most buildings over 75 ft in height be a fire tower.

"architect/engineers prepare a listing of the elements of the design which do not conform to old code requirements, but are acceptable under the new. With this list in hand, we could initiate discussions, at top level in the Building Department, to see if we can secure agreement to go along with our design (Kyle 1966)."

A one-page document, <sup>8</sup> dated "2/15/67", with the initials "CKP" listed the following items:

- 1. Fire tower corridors [sic] eliminated.
- 2. Number of stairs reduced from 6 to 3. (Old plans had 5 stairs at 3'-8" and 1 stair at 4'-8" for a total population of 390. New plans have 2 stairs at 3'-8" and 1 stair at 4'-8" allowing a population of 390.)
- 3. The size of doors leading to the stairs are [sic] changed from 3'-8" to 3'-0".
- 4. All stairs exit through a lobby. Old plans had fire tower stair exiting through a fire enclosed corridor.
- 5. Shaft walls are changed from a 3-hour rating to a 2-hour rating.
- 6. Corridors are limited to a 100' dead end and with a 2-hour rating.
- 7. Additional [word(s) missing] changed from 20 pounds per square foot to 6 pounds per square foot (based on partition weight of 50 pounds to 100 pounds per linear foot).

Apparently, the above list represents elements of the WTC design that would not have satisfied the 1938 code, but did satisfy the then-current draft version of the new code.

A letter dated February 18, 1975, from the architect-of-record to the Port Authority discusses compliance with the 1968 NYC Building Code (Solomon 1975). This letter begins with the following paragraph:

In accordance with the instructions issued by the Port Authority at the start of the project, construction drawings for the World Trade Center were to conform with requirements of the Building Code of New York City, and any variations therefrom were to be called to the attention of the Port Authority for final decision and authorization. This procedure has been followed in the production of the contract drawings and, with the exceptions authorized by the Port Authority noted below, the drawings are in accordance with the new Building Code adopted in December, 1968. The Building Department reviewed the tower drawings in 1968 and made six comments concerning the plans in relation to the old code. Specific answers noting how the drawings conformed to the new code with regard to these points were submitted to the Port Authority on March 21, 1968.

<sup>&</sup>lt;sup>8</sup> "Changes to Building to Conform to New New York City Building Code," dated 2/15/67.

The same letter continues with a list of four items that the architect was "instructed by the Port Authority to deviate from code (Solomon 1975)." The four items are:

- Omission of vents from closed shafts.
- Demising partitions to stop at suspended ceiling or bottom of truss instead of running from slab to slab.
- Omission of fire protected openings on exterior walls with separation of less than 30 ft.
- Treatment of the concourse level as Underground Street.

Section C26-504.3(a) of the 1968 NYC Building Code required that tenant spaces be separated "by fire separations having at least the fire resistance rating prescribed in table 5-1, but in no case less than 1 hr, and shall continue through any concealed spaces of the floor or roof construction above." The Port Authority chose to stop tenant (demising) partitions at the bottom of the suspended ceiling and use 10 ft strips of 1 h rated ceiling on either side of the partition (Solomon 1969). The general contractor stated in a letter to the Port Authority "...we have been unable to find any precedent for the fire rated ceiling 10' on either side of the demising partitions beyond the one you described from your construction experience on Port Authority hangers [sic] (Endler 1969)."

In a code compliance evaluation report written in 1997, it was stated "Tenant demising partitions, including separations from the public corridor, do not in all cases meet the requirement of being built to the slab above (Coty 1997)." The author of the report recommended that: "Generally, this condition has been and will continue to be remediated as a requirement of new tenant alterations. However, it is recommended that the Port Authority develop and implement a survey program to assure that this remediation process occurs as quickly as possible."

The tenant alteration guidelines issued in 1998 require that tenant partitions have a 1 h fire rating, and the standard details for fire rated partitions indicate a continuous fire barrier from top of floor to bottom of slab (PANYNJ 1998).

#### **Compartmentation and Sprinklers**

Neither the 1968 NYC Building Code nor any of the other contemporaneous codes that were examined required sprinklers in tall buildings except for underground spaces. Thus, only the parking garage under WTC 1 and WTC 2 was originally sprinklered. Although Local Law 16, adopted in 1984, required sprinklers in new office occupancies, it was not retroactive. The incentive to retrofit for sprinklers (as explained below) was the passage of Local Law 5 in 1973, which was retroactive.

In the 1968 NYC Building Code, Class 1B construction for business occupancies had no limit on floor area. Local Law 5 required compartmentation of large floor areas in existing business occupancies over 100 ft in height by the installation of fire rated partitions in accordance with the following:

- Compartmentation to 7,500 ft<sup>2</sup> with 1 h partitions; or
- Compartmentation to 10,000 ft<sup>2</sup> with 2 h partitions; or

• Compartmentation to 15,000 ft<sup>2</sup> with 2 h partitions and smoke detectors.

Compartmentation was not required, however, if "complete sprinkler protection" were provided. Compliance dates for these provisions were revised in 1979 by Local Law 84 so that one-third of the total area of buildings had to be in compliance by December 13, 1981, two-third of the total area had to comply by August 7, 1984, and full compliance was required by February 7, 1988.

Following the February 13, 1975, fire in the lower stories of WTC 1 (Powers 1975), an independent consultant was retained to review WTC life-safety provisions, including response to Local Law 5. It is reported that the "consultant concluded that the existing structural fire retardants of the building are sufficient to make the probability of serious structural damage extremely remote and the degree of vertical compartmentation provided sufficiently limits the spread of fire in the structures but that the spread of smoke requires attention from a life safety standpoint (PONYA 1976)." The consultant reported that "...either of the two fire protection options provided for under Local Law 5 would provide a good level of occupant life safety within the World Trade Center complex, provided that whichever is selected is supplemented by certain additional measures." The consultant provided a series of recommendations to supplement either the compartmentation option or the sprinklering option.

The Port Authority initially decided to adopt the compartmentation option in response to Local Law 5. The summary of the January 1976 report on the *Fire Safety of the World Trade Center* lists the following actions to be implemented to enhance the fire safety of the WTC towers (PONYA 1976):

- 1. The openings between floors of telephone closets, which was a source of fire spread during the February 13, 1975, fire should be closed. This work has been accomplished to prevent any reoccurrences of a similar condition.
- 2. In addition, the Port Authority will proceed with the compartmentation option of Local Law 5, including all of its requirements for fire alarm, communications, and stairway pressurization.
- 3. Sprinklering of all storage rooms, janitor closets, mail rooms and file rooms in the central core of each floor.
- 4. Building additional sprinkler capacity and provisions for extension of a sprinkler system to any area of such usage requiring it in the event of an occupancy change.
- 5. Equipping those doors which are normally kept open to the corridor system, such as doors at consumer service areas, with electromagnetic 'hold open' devices which would be activated by smoke detectors to close the doors.
- 6. Providing fail-safe automatic door closers, arranged to close upon activation by smoke detectors, for the overhead rolling fire doors separating the below-grade truck dock from the elevator lobby.

7. Developing an optimum mode of operation of the building air-conditioning system to remove smoke from the central core compartments without contaminating adjacent areas.

Thus, while the Port Authority initially chose to implement the compartmentation option, it also chose to provide "for extension of sprinkler system to any area of such usage requiring it." According to the 1993 joint report written by the NYC Fire Commissioner and Commissioner of Buildings, in the 1980s the Port Authority began "a program to fully sprinkler the Tower buildings (Rivera and Rinaldi 1993)." The report goes on to state that by March 1993 sprinklering was "nearly complete in Tower 2 and 85 percent complete in Tower 1." The report also included a table that summarized "the major system requirements of Local Laws 5/73 and 16/84 with conditions in place when the 1993 explosion occurred." The content of that table is reproduced here as Table 2–2.

The tenant alteration guidelines issued in 1998, contained the following requirement and information (PANYNJ 1998):

All tenant spaces shall be sprinklered. Except for a few areas, most tenant floors in The World Trade Center are provided with wet-pipe sprinkler systems. New tenants normally require a new sprinkler system. For renovations of existing spaces, modifications to the existing system are normally needed to comply with any new partition configuration.

Because Local Law 16 required that business occupancies taller than 100 ft be sprinklered, WTC 7 was sprinklered during the original construction.

#### **Emergency Egress**

The 1968 NYC Building Code has requirements for the number and capacity of stairs and for the assumed occupant load that are similar to requirements in the other contemporaneous codes (see Appendix A). Codes of the time required that multiple stairs be located "as remote from each other as practicable." NYC permits scissor stairs, and the code requires the exit doors to be at least 15 ft apart. Local Law 16 (1984) first imposed a remoteness requirement of 30 ft or one-third the maximum travel distance of the floor (whichever is greater), which was not retroactive, so it did not apply to WTC 1 and WTC 2 but did apply to WTC 7.

The 1968 NYC Building Code also has a requirement that, "...vertical exits should extend in a continuous enclosure to discharge directly to an exterior space or at a yard, court, exit passageway or street floor lobby ..." (C26-602.4). Similar requirements are found in the 1965 BOCA Basic Building Code and in 1966 NFPA 101, but not in the 1964 New York State Building Construction Code or the 1966 Municipal Code of Chicago. Current code language (2003 IBC, section 1003.6) defines continuous as: not "... interrupted by any building element other than a means of egress component."

This requirement was the subject of ongoing discussion with respect to the stairs in WTC 1 and WTC 2 discharging onto the mezzanine level, which was not at street level but rather at the Plaza level. It was the

-

Scissor stairs refers to two separate interior stairways contained within the same enclosure and separated by a fire rated partition.

position of the Port Authority that the Plaza was like a street, and the arrangement met the intent of the Code.

Table 2–2. Summary of compliance with Local Laws 5/73 and 16/84 provided in March 1993 report by Fire Commissioner and Commissioner of Buildings (Rivera and Rinaldi 1993).

	(Rivera and Rinaidi 1993).							
	Type of Work {Code Section}	Compliance						
1	Compartmentation {504.1(c)}	Not required in sprinklered buildings						
2	Smoke shaft of stair pressurization {504.15(c)}	Not required in sprinklered buildings. However, smoke purge and pressurization of corridors with 100% fresh air is provided.						
3	Emergency power exit lights {605.2(b)}	Exceeds requirement.  Required — On separate circuit ahead of main switch  Provided — Separate feeders and emergency generators (NOTE A)						
4	Emergency power exit signs {606.2(b)}	Exceeds requirement.  Required — On separate circuit ahead of main switch  Provided — Separate feeders and emergency generators (NOTE A)						
5	Stair and elevator signs {608.0}	Yes						
6	Emergency power {610.0}	Exceeds requirement.  Required — None  Provided — See NOTE A above						
7	Sprinklers {1703.1}	Yes 95% completed for one tower [WTC 2] 85% completed for other tower [WTC 1]						
8	Class "E" fire alarm signal system {1704.5(f)}	Yes — But air supply and exhaust air to fire floor are not closed off when sprinklers are activated.  Note: equivalent system provided by item #2 above and smoke detectors at fans, which stop fans.						
9	Fire command and communication {1704.8}	Yes — except that each building does not have its own fire command station						
10	Elevator in readiness {1800.8(b)}	Yes — See NOTE A above						
11	Removal of locks on elevators and hoistway doors {1801.4}	Yes						
12	Firemen's service operation {1801.5}	Yes — See NOTE A above						

## **Fire Alarm Systems**

Consistent with practice at the time, the original fire alarm system in WTC 1 and WTC 2 was a manual system with four smoke detectors on each tenant floor, positioned to monitor for smoke entering the HVAC returns and arranged to stop the fans to prevent smoke circulation to non-fire areas. Local Law 5 (1973) included retroactive requirements for fire alarm systems and emergency voice communication systems in business occupancies over 100 ft in height. Subsequently, such systems were installed in WTC 1 and WTC 2 with the required fire command center located in the underground parking garage. Following the 1993 bombing, the fire command stations were relocated to the tower building lobbies with a third monitoring location in the Port Authority offices. There are no code requirements for off-site monitoring of fire alarm systems in this occupancy.

## **Elevators**

Local Law 5 requires that elevators be provided with an emergency recall system. This requirement was incorporated subsequently into the American Society of Mechanical Engineers (ASME) A17.1, Safety Code for Elevators and Escalators, that governs elevator design and operation in all the building codes. The ASME Code requires that:

- All passenger elevators be marked with signs stating that they cannot be used during a fire;
- Fire detectors installed in every elevator lobby and machine room be arranged to initiate a recall of the elevators to the ground floor where the doors open and the elevator is taken out of service; and
- Fire service personnel can use a special key to operate any individual car in a manual mode as long as they feel it is safe to do so.

The elevator and building codes require that at least one elevator serving every floor be connected to emergency power. Refer to Table 2–2 for elevator status in WTC 1 and WTC 2 in 1993.

## **Structural Stability**

As discussed in Appendix A, provisions related to structural stability in the 1968 NYC Building Code were in general agreement with those of the contemporaneous codes that were compared. There were, however, a number of provisions in the NYC code that were not included in the other codes such as uniform partition dead loads based on the weight of the partitions, consideration of loads due to thermal expansion/contraction and shrinkage of concrete, minimum strength requirements for bracing of compression members, and allowance for design wind loads based on wind tunnel tests. The NYC code, however, does not provide a standard protocol for wind tunnel testing to establish design wind loads.

#### 2.2.6 WTC 7 Fuel System

WTC 7 was constructed and owned by Silverstein Properties on land owned by the Port Authority. It was built and operated by Silverstein as a Port Authority tenant alteration (see Appendix A.1). Many of the tenants conducted critical business operations in the building and required uninterruptible power to

prevent the loss of information or operational continuity in the event of a power failure. This backup power was provided by diesel generators located in the mechanical spaces of the building. These generators were designed to start automatically in the event of an interruption of the utility supply. The total generator capacity and quantity of fuel stored in the building was sized to tenant needs.

#### **Code Requirements**

Design and installation of the WTC 7 emergency power and associated fuel systems were to follow the NYC Building Code. The base system was installed in 1987 with modifications occurring in 1990, 1994, and 1999. Over the period 1987 to 1999, the NYC Building Code provisions discussed below were not changed, so all systems were installed to the same requirements. Some of the key code provisions for the construction and location of fuel storage tanks, piping, and controls are discussed here, and additional details will be published in a separate report.

## Tanks [27-828 and 27-829] 10

All tanks must be fabricated of steel and coated to prevent corrosion. Minimum thicknesses are specified by tank diameter for storage tanks and for so-called "day tanks" (60 gal or 275 gal). Large storage tanks (up to 20,000 gal) may be buried inside or outside the building or on the lowers floor of the building with protection related to the tank capacity. For example, tanks from 550 gal to 1,100 gal must be enclosed in 2 h fire rated, noncombustible construction and tanks larger than 1,100 gal in 3 h construction.

Tanks on floors above the lowest floor are limited to 275 gal and one such tank per story. These "day tanks" must be surrounded by a concrete curb or steel pan with the capacity to hold twice the volume of the tank in the event of a leak. The curb or pan must be provided with a float switch to sound an alarm and shut off the transfer pump in case of tank failure. Appropriate controls (generally a float switch in the day tank) are provided to transfer fuel from the storage tanks to the day tank through a transfer pump and piping, with only one such transfer pump and piping network per day tank.

## Piping [27-830]

Piping from transfer pumps to day tanks is required to be enclosed in a shaft of 4 in. thick concrete or masonry with a 4 in. clearance to the fuel pipe. Horizontal offsets may be enclosed in a steel sleeve two (pipe) sizes larger and enclosed in 2 h fire rated construction. The spaces between the fuel pipe and sleeve or shaft must lead to an open sight drain or an open sump so leaks can be detected.

## **Power Systems Designs**

NIST located and reviewed specifications and drawings for each of the emergency power systems. It was noted that some of the fuel risers were installed in existing shafts containing other utilities. The NYC Building Code requires that pipe shafts containing piping from the transfer pump to storage tanks above the lower floors not be penetrated by or contain other piping or ducts [27-830(f)(5)]. Correspondence relating to the system for the Mayor's Office of Emergency Management shows that this system was

\_

Sections of the New York City Building Code in which these requirements are found. These provisions are found in the subchapter on "Heating and Combustion Equipment."

reviewed and inspected by the FDNY, a list of needed corrections was produced, and each item was initialed as the corrections were verified.

## **Base Building System**

The initial base emergency power system was installed in 1987, and consisted of two 900 kW generators and a 275 gal day tank located on floor 5. Main fuel storage was in two 12,000 gal tanks buried under the loading dock on the south side of the building. The tanks were double wall fiberglass<sup>11</sup> with leak detectors between the walls.

Fuel was transferred by one of the two pumps through a 2 in. supply line in an existing shaft containing other utilities, near the west bank of passenger elevators. The transfer pump was controlled by a float switch in the day tank with a low (pump on) and high (pump off) position. An alarm would be sounded if the fuel level in the day tank fell below the low level or went above the high level. The day tank was located within a 550 gal pan fitted with an alarm and another pump cutoff. The vent for the day tank terminated outside the south wall.

The 2 in. fuel lines were encased in a second pipe covered with 2 in. of calcium silicate to provide the required 2 h fire rating. Pipe supports were located approximately 10 ft apart, and inspection plugs were provided approximately 50 ft apart. Mechanical equipment rooms were sprinklered (ordinary hazard group I), and the fuel pump room was sprinklered (ordinary hazard group III). The generator area on floor 5 was not sprinklered.

## **Modifications to System**

From 1990 to 1999, four major modifications (additions) were made to the base emergency power system. These modifications are summarized in Table 2–3. Of significance are the 1990 modification (Salomon Brothers) that required a pressurized fuel supply system, because a day tank already existed on floor 5, and the 1999 modification (Mayors' Office of Emergency Management) that required a separate 6,000 gal tank on the first floor. Figure 2–1 is a schematic of the locations of the various components of the base system and the four major modifications.

For the Salomon Brothers system, the transfer pumps were powered from the output of the generators. In the event of a failure of utility power, all nine generators were started automatically to ensure that if any of the nine did not start there would be enough power. Once the generators were up to speed, the control system would shut down those that were not needed, but these could be restarted later if power demand increased. There was enough fuel and residual pressure in the lines to start the generators and to run them for a few minutes, but once running, the fuel pumps were powered to supply fuel. As long as any one generator was running, the pumps ran at full capacity.

\_

<sup>&</sup>lt;sup>11</sup> While the NYCBC requires steel tanks, effective in November of 1985 the U.S. Environmental Protection Agency required (40CFR280) that all new underground fuel storage tanks be double wall fiberglass and that any steel tanks older than 20 years be replaced by double wall fiberglass.

Table 2–3. Summary of modifications to base emergency power system in WTC 7.

Year	Day Tank/Generator	Storage Tank	Piping	Comments
1990	No day tank permitted since base design included one on floor 5/9 generators on floor 5, 1750 kW combined capacity	Two 6,000 gal next to base tanks.	Two 2 1/2 in. pipes in separate rated shaft	50 psi pressurized fuel system
1994	50 gal/125 kW on floor 9; generator room sprinklered	Used existing base tanks	1 1/4 in. in new 2 h rated dedicated shaft	New transfer pump connected to existing storage tanks
1994	275 gal/350 kW on floor 8; generator room sprinklered	Used existing base tanks	2 in. in same dedicated shaft as above	New transfer pump connected to existing storage tanks
1999	275 gal/three 500 kW on floor 7; smoke detectors in generator room	6,000 gal on floor 1, in 4 h rated enclosure; gaseous (clean) fire suppression system; space below tank sprinklered	10 gauge conduit in 2 h rated enclosure	Storage tank kept filled from base storage tanks.

## 2.2.7 Preliminary Findings

The following preliminary findings are based on (1) review of the design and construction documents of WTC 1, 2, and 7; (2) review of the 1968 NYC Building Code, the 1964 New York State Building Code, the 1967 Municipal Code of Chicago, the 1965 BOCA Basic Building Code, and the 2001 NYC Building Code; and (3) correspondence of the Port Authority, design consultants, and general contractor.

1. Building code used for design of WTC 1, 2, and 7

When the design of WTC 1 and WTC 2 began in 1962, the governing building code in NYC was the 1938 edition. In September 1965, the Port Authority instructed its consultants to revise their design for WTC 1 and WTC 2 to comply with the second and third drafts of the new building code of NYC that was under development (Levy 1965). The new building code was adopted on December 6, 1968.

The Port Authority took advantage of some of the less restrictive provisions of the 1968 Code compared with the outdated 1938 Code. Some of these new provisions included:

- a. Elimination of a fire tower as a required means of egress;
- b. Reduction in the number of required stairs;
- c. Reduction in fire rating of shaft walls from 3 h to 2 h;
- d. Use of uniform partition load that depends on weight of partition per unit length; and




Figure 2–1. Locations of emergency generators and fuel tanks in WTC 7.

e. Allowance of Class 1B construction for business occupancy and unlimited building height.

One of the reviewed documents noted that "For office buildings there is <u>no</u> economic advantage in using Class 1A Construction, and ER&S [architect-of-record] used Class 1B Construction for the WTC Towers and Plaza Buildings...." (Feld 1987).

The design of WTC 7 followed the 1968 code as amended by Local Laws, which includes Local Law 16, requiring sprinklers in buildings taller than 100 ft.

#### 2. Review of design documents by the Department of Buildings of NYC

In 1963, the Port Authority instructed its consultants that the design of the WTC should comply with NYC Building Code. The Port Authority also stated that: "When preliminary designs have been completed, the Chief Engineer will review all design concepts with the appropriate municipal agencies before the consultants proceed with the final design (Levy 1963)." This implies that the NYC Department of Buildings would be involved in reviews of the design. A letter in 1975 from the architect-of-record to the Port Authority indicates that in 1968 the NYC Department of Buildings reviewed the tower drawings and "made six comments concerning the plans in relation to the old code (Solomon 1975)." It was stated further that on March 21, 1968, the architect submitted to the Port Authority responses to these comments "noting how the drawings conformed to the new code." NIST is attempting to locate a copy of this correspondence to determine, if possible, the level of review conducted by the Department of Buildings and the specific six items identified in that review.

#### 3. The 1968 NYC Building Code compared with contemporaneous codes

The 1968 NYC Building Code was more comprehensive in the coverage of provisions in certain areas compared with the other contemporaneous codes that were reviewed. For example, the 1968 NYC Building Code requires special design consideration for expansion and contraction due to temperature and shrinkage of concrete, and it permits determination of design wind loads from tests. In general, except for permitted construction classifications, provisions for structural stability, fire safety and egress were similar among the four contemporaneous codes that were compared (see Appendix A.5.1 and A.5.2 for details). There were, however, differences in permitted live load reduction, design wind pressures, and the treatment of partition loads. Table A–8 in Appendix A provides a summary of fire safety provisions for high-rise buildings used for business.

In the 1993 joint report, the Fire Commissioner and Commissioner of Buildings made this comment about the NYC Building Code (Rivera and Rinaldi 1993):

We pride ourselves that our codes are among the most stringent in the nation, and we have been in the forefront in applying technological advances to assure fire and structural safety in buildings.

#### 4. Permitted construction classification for high-rise buildings

The 1938 NYC Building Code permitted only Class 1 (fireproof) construction for unsprinklered office buildings of unlimited height and area, which required a 4 h fire rating for columns and a 3 h rating for floor framing members (4-3 rated construction). The 1968 New York Building Code subdivided Group 1 (noncombustible) construction into Class 1A and 1B. Class 1B required a 3 h fire rating for columns and a 2 h rating for floor framing members (3-2 rated construction). There was precedence in earlier model building codes for permitting 3-2 fire rated construction for unsprinklered high-rise office buildings (BOCA 1950 and SBCC 1946). Of the contemporaneous codes that were reviewed, the 1964 New York State Building Code and the 1965 BOCA Basic Building Code permitted 3-2 rated construction for unsprinklered office buildings of unlimited height and area. The 1967 Chicago Municipal Building Code permitted only 4-3 rated construction for high-rise office occupancy. (See Appendix A.4.4 for more detail.)

## 5. Deviations from NYC Building Code

In 1975, the architect-of-record wrote a letter to the Port Authority pointing out that the Port Authority had provided instructions to deviate from the NYC Building Code with respect to four items (Solomon 1975). One of these was a deviation from the requirement that tenant fire-rated partitions be continuous from floor to floor. Over the years, these partitions were replaced with partitions that were continuous as required by the 1968 Code. In the 1997 report on code compliance, it was noted that some partitions did not meet the requirement (Coty 1997). The 1998 tenant alteration guidelines require that core walls have a 2 h fire rating and walls separating tenants (demising walls) have a 1 h rating (PANYNJ 1998). The standard details for 2 h and 1 h rated partitions show that the partitions provide a continuous fire barrier from top of floor to underside of slab.

#### 6. Compartmentation and sprinklering

Following the passage of Local Law 5 in 1973, the Port Authority implemented a program to proceed with the compartmentation option of Local Law 5 and to provide for the extension of the sprinklering system beyond the below grade spaces installed during original construction. In addition, sprinklers were installed in storage rooms, janitor closets, mailrooms and other spaces in the core area of each floor, and outside the core for tenants not selecting the compartmentation option. In the 1980s, the Port Authority began a program to sprinkler the remaining tenant spaces, initially as tenants changed, and later on negotiated schedules. According to Local Law 86, passed in 1979, full compliance with Local Law 5 was required by February 7, 1988. A report in 1997 states that there were four floors and the sky lobbies (all in WTC 1) that remained to be sprinklered, and that installation of sprinklers on these floors was in progress (Coty 1997). In the October 1999 report on code compliance, it is stated that sprinklering of the tenant floors was completed and sprinklering of the sky lobbies was "currently under way" (PANYNJ 1999). The tenant design guidelines in 1998 require that all tenant spaces be sprinklered (PANYNJ 1998).

#### 7. Fuel system for emergency generators in WTC 7

The generators and associated fuel distribution system installed in WTC 7 followed the requirements of the NYC Building Code with two exceptions. First, the underground storage tanks were fiberglass and not steel, but this is consistent with federal requirements promulgated by the U.S. Environmental Protection Agency, which preempt the City requirements. The second deviation was the installation of the fuel risers for the base system in an existing shaft with other utilities. All of the subsequent sets of fuel risers were installed in a separate 4 h rated shaft.

The modification in 1990 included a pressurized fuel system, and the generators powered the fuel pumps. As long as one generator was running, the pumps ran at full capacity.

## 2.3 BASELINE STRUCTURAL PERFORMANCE AND AIRCRAFT IMPACT DAMAGE ANALYSIS (PROJECT 2)

## 2.3.1 Project Objective

Project 2 of the NIST investigation into the collapse of the WTC towers focuses on (1) establishing the baseline structural performance of each of the two towers under design gravity and wind loads and (2) analyzing the aircraft impacts into each of the two towers to estimate the damage to the towers and establish the initial conditions for the fire dynamics modeling in Project 5 and thermal-structural response and collapse initiation analysis in Project 6. The objective of the project is to evaluate the role of the structural system and the abnormal loads from aircraft impact on the collapse of the WTC towers by (1) developing reference structural models of the WTC towers that serve as reference for more detailed models to be developed for Projects 2 and 6, (2) using these models to establish the baseline performance of each of the towers under design loading conditions, (3) estimating probable damage to the structural, mechanical, and architectural systems of the towers due to aircraft impacts, (4) evaluating the role of floor diaphragms and hat trusses on the structural integrity of the towers, and (5) estimating the structural reserve capacities of the towers under service loading conditions after losing a number of exterior and core columns and floor segments due to aircraft impact.

## 2.3.2 Project Approach

This project is divided into two primary focus areas. The first, related to establishing the baseline performance of the towers under design loading conditions, is divided into the following tasks:

- Develop Structural Databases of the Primary Components of WTC 1 and WTC 2. To develop electronic databases for the major structural components of the WTC towers from original computer printouts of the structural design documents and modifications made after construction. This task will also estimate all cross-sectional properties and link the databases into a format suitable for the development of the reference structural models of the towers.
- Develop Reference Structural Analysis Models of WTC 1 and WTC 2. To use the structural databases to develop finite element structural models of WTC 1 and WTC 2 that capture the intended behavior of the towers. The models include typical floor models and

global models of the towers. The models are used to establish the baseline performance of each of the towers under gravity and wind loads and serve as reference for more detailed structural models to be used for other phases of the investigation.

- Estimate Wind Loading Criteria on the WTC Towers Based on the State of the Art. To develop wind loads on the towers based on currently available aerodynamic information (from two wind tunnel tests conducted recently by parties to an insurance litigation concerning the towers) and on extreme climatological information from available data and applicable standards.
- Establish the Baseline Performance of WTC 1 and WTC 2 Under Design Loading Conditions. To use the reference structural models to analyze the two towers to estimate stresses, deflections, and member utilization ratios under the following loads:
  - Gravity loads considering the following cases: (1) dead loads, (2) live loads used in the original design of the towers, and (3) live loads according to the current American Society of Civil Engineers (ASCE) 7 Standard.
  - Lateral wind loads considering the following cases: (1) wind loads used in the original design of the towers, and (2) wind loads based on the state of the art.

The second focus area, related to analyzing the aircraft impacts into each of the two towers, is divided into the following tasks:

- Analyze the Aircraft Impacts into WTC 1 and WTC 2. To analyze the aircraft impact into each of the two towers to provide the following: (1) estimates of the damage to structural systems due to aircraft impact including exterior walls, floor systems, and interior core columns; (2) estimates of the aircraft fuel dispersal during the impact; (3) estimates of accelerations and deformations in each of the two towers due to aircraft impact to be used for estimating damage to fire proofing; and (4) a database of the major fragments of the aircraft and destroyed structural components of the towers to be used for estimating damage to the mechanical and architectural systems inside the towers. The impact analyses are conducted at various levels including: (1) the component level, (2) the subassembly level, and (3) the global level to estimate the probable damage to the towers due to aircraft impact. The analyses also include simplified and approximate methods. This task will include the development of detailed models of the aircraft and the towers at the impact zone.
- Analyze the Post-Impact Stability of WTC 1 and WTC 2. To examine the stability of each of the two towers and determine the reserve capacity after losing columns and floor segments due to aircraft impact and show that the towers did not collapse immediately after impact. The analyses will help understand the mechanism by which the towers remained standing after impact, including the load redistribution provided by the hat truss system, and determine how close to collapse were each of the towers immediately after impact.
- Perform Sensitivity and Probabilistic Analysis of Aircraft Impact. To (1) conduct a sensitivity analysis to assess the effects of variability associated with various input parameters and identify the most influential parameters that affect the damage estimates and

(2) perform probabilistic analysis to determine the probabilities associated with different damage estimates.

Work completed to date on the above tasks is summarized in the following sections.

#### 2.3.3 Development of Structural Databases for WTC 1 and WTC 2

The development of structural databases of the primary components of the towers has been completed under a contract from NIST by the firm of LERA, the firm responsible for the structural engineering of the WTC towers. The work included digitization of the original drawing books with tabulated information, a quality control procedure to ensure consistency of the generated databases with original design documents, cross sectional property calculations, and developing relational databases to link the database files into a format suitable for models development. The developed databases include modifications made after construction.

NIST has implemented a rigorous review procedure to mitigate potential conflicts of interest and to ensure the integrity and objectivity of the deliverables. The review procedure includes an in-house NIST review and a third-party review by the firm of Skidmore, Owings, & Merrill (SOM) also under a contract from NIST. The third-party review by SOM included random checks of the digitized structural databases and cross section property calculations. The review indicated no discrepancies between the developed databases and the original drawing books. The in-house NIST review included: (1) line-by-line review of all database files, (2) random checks on the developed databases by project leader, and (3) calculation of all cross section properties and comparing with those in the developed databases. The review indicated minor discrepancies between the developed databases and the original drawing books. These discrepancies were reported to LERA, who implemented the changes and modified the databases accordingly. Consequently, the structural databases have been approved by NIST and are being made available for other phases of the NIST investigation.

Additional details on the development of the structural databases appear in Appendix B.

## 2.3.4 Development of Reference Structural Models for WTC 1 and WTC 2

The development of the reference structural models for the towers has been completed by LERA. These are three-dimensional, linear, finite element models (FEMs) of the towers developed using SAP2000 software. The models include:

- Typical truss-framed floor model (floor 96 of WTC 1): The model contains all primary structural members of the floor system, including primary and bridging trusses, beams in the core, strap anchors, viscoelastic dampers, exterior and core columns above and below floor level, spandrel beams, and concrete slabs. Initial verification of the model has also been performed.
- Typical beam-framed (mechanical) floor model (floor 75 of WTC 2): The model contains all
  primary structural members of the floor system, including composite beams, horizontal
  trusses, viscoelastic dampers, exterior and core columns above and below floor level,
  spandrel beams, and concrete slabs. Initial verification of the model has also been performed.

• Global models of each of the two towers: These are models of the 110-story above grade and 6-story below grade structure for each of the two towers and include the following six main parts: core columns, exterior wall (foundation to floor 7), exterior wall trees (floors 7 to 9), exterior wall (floors 9 to 106), exterior wall (floors 107 to 110), and hat trusses. These models were developed separately and then assembled into a unified model. Rigid and flexible diaphragms representing the floor systems, core bracing, and loads were then added to the unified model. Parametric studies were undertaken to establish the idealizations used in the global models. These studies included detailed shell element and simplified beam element models for typical exterior wall panels and exterior corner panels. The parametric studies also included development of a simplified flexible floor diaphragms calibrated against the detailed floor models. Initial verification of the global models has also been performed.

Similar to the structural databases, the developed reference models were thoroughly reviewed. As part of the review process, NIST conducted a workshop for NIST investigators, outside experts, and contractors to review the reference structural models developed by LERA. The purpose of the workshop was to discuss the methodology, assumptions, and details of the developed reference models. The feedback from individual workshop participants was included in the final review of the models.

The in-house NIST review and the third-party review by SOM included: (1) checks on the consistency of the developed reference models with the original structural drawings and drawing books, and (2) verification and validation of the models, including reviewing assumptions and level of detail and performing analyses using various loading conditions to assess the accuracy of the models. The reviews indicated minor discrepancies between the developed reference models and the original design documents. The reviews also indicated that, in general, the modeling assumptions and level of detail in the models were accurate and suitable for the purpose of the project. The reviews identified two areas where the models need to be modified. The first is the effect of additional vertical stiffness of the exterior wall panels due to the presence of the spandrel beams. The second area is the modeling of the connections of the floor slab to the exterior columns of the typical beam-framed floor model, where this connection appeared to be fixed while the connection should be modeled as pinned. The minor discrepancies and the areas identified for modification were reported to LERA, who implemented the changes and modified the models accordingly. Consequently, the reference structural models have been approved by NIST and are being made available for other phases of the NIST investigation.

More details on the development of the reference structural models appear in Appendix B.

#### 2.3.5 Estimates of Wind Loads on the WTC Towers

The development of estimates of wind loads on the WTC towers has been completed by NIST on the basis of the current state of the art in wind engineering. The estimates make use of wind tunnel test results and extreme wind climatological estimates obtained by Rowan Williams Davis and Irwin, Inc. (RWDI) and by Cermak Peterka Peterson, Inc. (CPP) as part of insurance litigation concerning the WTC towers. In addition, the estimates of wind-induced forces and moments on the WTC towers make use of independent extreme wind climatological estimates performed by NIST, based on airport wind speed data obtained from the National Climatic Data Center, National Oceanic and Atmospheric Administration, and on the NIST hurricane wind speed database.

A comparison of estimates by CPP and RWDI of wind-induced maximum base moments on WTC 2 indicates a difference of about 40 percent between the two estimates. NIST studied the two wind tunnel reports and attempted to identify the sources of disagreement between them in order to develop the wind loading on the towers. The NIST study included: estimates of the wind speeds for the direction that corresponds in the CPP and RWDI reports to the peak wind-induced base moment, and a critique of wind profiles used in estimation of wind loads by RWDI and methods used to integrate aerodynamic and extreme wind climatological data (the sector-by-sector approach in the CPP report and the up-crossing method in the RWDI report).

The wind load estimates are currently being reviewed by SOM. Upon completion of the third-party review, the loads will be applied to the global models of the towers as part of the baseline analysis.

## 2.3.6 Baseline Performance Analysis of the Towers

Work is under way to complete this portion of the study. Significant progress has been made in using the reference models subject to gravity loads (dead loads and live loads used in the original design and according to ASCE 7-02 Standard) and wind loads used in the original design of the towers. Upon completion of loads application into the models, the models will be analyzed to establish the baseline performance of the towers. The results of the analysis will be reported at a later date.

## 2.3.7 Analysis of Aircraft Impacts into WTC 1 and WTC 2

The objective of the analysis of aircraft impacts into the WTC towers is to estimate the impact response of the towers, including damage to structural systems, acceleration environment, and fuel and debris dispersion. The analysis is being conducted at various levels including: (1) the component level, (2) the subassembly level, and (3) the global level to estimate the probable damage to the towers due to aircraft impact. The analyses also include simplified and approximate methods. NIST is working with experts from Applied Research Associates, Inc. (ARA) under a contract from NIST to conduct these analyses. The commercially available finite element analysis (FEA) software, LS-DYNA is being used for most impact analyses in this project.

The development of constitutive models describing the actual behavior of the structure under the dynamic impact conditions of the aircraft is an important step prior to conducting the impact analyses. Significant progress has been made to identify the proper constitutive relationships, including high strain-rate effects and failure criteria for the various materials included in the analysis of aircraft impacts into the WTC towers. These materials include the various grades of steels used in the exterior walls and core columns of the towers, weldment, bolts, reinforced concrete, and aircraft materials. Details on the development of the materials constitutive models appear in Appendix C.

Another important step prior to conducting the various impact analyses is the development of an aircraft model to be used in the component, subassembly, and global analyses. The model is developed based on information gathered from documentary aircraft structural information, and data from measurements on a Boeing 767 aircraft. The development of the Boeing 767 aircraft model for impact analysis is nearing completion. The engine and wing models have been completed and are being used in the component and subassembly analyses. Also completed is the empennage and landing gears. Work is under way to

finalize the model of the fuselage, nose, and nonstructural components of the aircraft. Details on the development of the aircraft model appear in Appendix C.

The WTC towers and Boeing 767 aircraft are complex structural systems, and a large database of detailed structural information has been collected on them. In the model development process, the objective was to include all of the primary structural components and details of both the aircraft and towers. This approach, however, results in very large models. The component and subassembly analyses were used to determine model simplifications that can reduce the overall model size while maintaining fidelity in the analysis. Therefore, a series of component impact analyses were performed. The primary objectives of component modeling are to (1) develop understanding of the interactive failure phenomenon of the aircraft and tower components and (2) develop the simulation techniques required for the global analysis of the aircraft impacts into the WTC towers, including variations in mesh density and numerical tools for modeling fluid-structure interaction for fuel impact and dispersion. The approach taken for component modeling is to start with finely meshed, brick element models of key components of the tower structure and progress to relatively coarsely meshed beam and shell element representations that will be used for the global models. Much progress has been made on the component level analyses using models of tower exterior and core columns with column end bolted connections and spandrel bolted connections, as well as floor segments impacted separately with an engine or a wing section with and without fuel. This analysis is nearing completion, and details on the analysis methodology and results appear in Appendix C.

Not reported in Appendix C is progress made on the subassembly analysis. This work is under way. Preliminary subassembly engine impact analyses into a strip from the exterior wall to the core of WTC 1 have been performed. An example analysis, shown in Fig. 2–2, is for a 500 mph engine impact centered on the spandrel for exterior panel 121A at floor 96 and includes core columns 503A and 603A between floors 94 and 98. This model includes a single width exterior panel and floor assembly of the same width. The concrete slab is modeled with brick elements, and the diagonal round bar members in the floor trusses are modeled with beam elements. The remainder of the structures, including the columns, metal decking, and truss upper and lower chord components, are modeled with shell elements. An alternate view of the impact damage at 0.25 s is shown in Fig. 2–3. Current work focuses on expanding the size of the model in width (larger number of exterior panels), height (larger number of floors), and depth (extension all the way through the core) to minimize the effect of boundary conditions on the model response. Details of further work on the subassembly analysis will be reported at a later date.

Also not reported in Appendix C is progress made on the development of the models of the towers in the impact zone to be used for the global impact analysis. This work is ongoing. Examples include single floor models in the core (Fig. 2–4), multiple floor models (Fig. 2–5), and exterior wall models (Fig. 2–6). Details of further work on the development of the global models will be reported at a later date.

#### 2.3.8 Preliminary Stability Analysis of the WTC Towers

Preliminary system stability analyses of the WTC towers have been performed to: (1) examine the overall stability of the undamaged tower upon removal of floors, (2) study possible load redistribution mechanisms upon losing columns in the core due to aircraft impact, and (3) study the response of WTC 1 when columns in the exterior walls and the core are assumed destroyed due to aircraft impact and columns in the exterior are damaged due to subsequent fire effects.




Figure 2–2. Example engine impact subassembly analysis.




Figure 2–3. Oblique view of the subassembly engine impact damage.




Figure 2–4. Model of the 96th floor and columns of WTC 1.




Figure 2–5. Model of the core of WTC 1, floors 94–98.




Figure 2–6. Detail of the WTC 2 impact zone exterior column panels.

The analyses used the typical truss-framed floor model and a reduced version of the global reference model of WTC 1 (see Section 2.3.4) with proper modifications. Modifications included adding vertical springs at the bottom of the reduced models to account for the removed lower portion of the towers, and using actual steel properties and actual loads on the towers. The analyses used staged construction technique to account for the sequential construction of the towers, especially in the zone of the hat trusses. Linear buckling analysis and nonlinear analysis with plastic hinges were used to study the effects of removal of floors and loss of exterior and core columns, respectively. In addition, analysis of the floor system, where severed core columns were replaced by equivalent springs representing the stiffness of the hat trusses and columns between the floors and hat trusses, was conducted to study the mechanism by which the floor loads were redistributed when the core columns were severed by aircraft impact.

Details on the preliminary stability analyses appear in Appendix D.

### 2.3.9 Summary and Preliminary Findings

Significant progress has been made on the first focus area of this project dealing with the baseline performance of the WTC towers. This includes the completion, review, and, final approval by NIST of the structural databases and reference structural models of the towers. Also completed are the NIST estimates of the wind loading on the towers based on the state-of-the-art, which is currently under review. Progress has been made on performing the baseline analysis.

For the second focus area, dealing with aircraft impact into the towers, work is nearing completion on the development of materials constitutive modeling, aircraft model, and component level analyses. Progress has been made on the subassembly and global models development. In addition, preliminary stability analyses of the towers under damage from aircraft impact have been performed.

The following presents some preliminary findings obtained from the component impact analyses (see Appendix C):

- A 500 mph engine impact against an exterior wall panel results in a penetration of the exterior wall and failure of impacted exterior columns. If the engine does not impact a floor slab, the majority of the engine core will remain intact through the exterior wall penetration with a reduction in velocity of about 10 percent and 20 percent. The residual velocity and mass of the engine after penetration of the exterior wall is sufficient to fail a core column in a direct impact condition. Interaction with additional interior building contents prior to impact or a misaligned impact against the core column could change this result.
- A normal impact of the exterior wall by an empty wing segment from the wing tip region will
  produce significant damage to the exterior columns, but not necessarily complete failure. A
  fuel-filled wing section impact results in extensive damage to the exterior wall, including
  complete failure of the exterior columns. This is consistent with photographs showing the
  exterior damage to the towers due to impact.
- Three different numerical techniques were investigated for modeling impact effects and dispersion of fuel: (1) standard Lagrangian FEA with erosion, (2) Smoothed Particle Hydrodynamics (SPH) analysis, and (3) Arbitrary-Lagrangian-Eulerian (ALE) analysis. Of these approaches, SPH analyses appear to offer the greatest potential for modeling fuel in the

global impact analysis due to the combination of both computational efficiency and modeling fidelity.

The following presents some preliminary findings obtained from the preliminary stability analyses under service live loads and subject to the assumptions and the limitations of these models (see Appendix D):

- Linear stability analysis was used to examine the stability of the undamaged WTC 1 under service loads through increased unbraced column lengths (floor removal). The tower was stable when two floors were removed. Two core columns buckled when three floors were removed, but the tower maintained its overall stability. The tower also maintained its stability when four columns buckled with four floors removed. The analysis suggested that global instability of the tower occurred when five floors were removed from the model. Assuming that all columns at the region of the removed floors reached a temperature of 600 °C (reduced modulus of elasticity), the analysis indicates that removal of four floors would induce global instability.
- Analysis of the typical truss-framed floor model with fifteen severed core columns indicated that, under service loads, the floors first attempted to redistribute their loads to the hat trusses through tension in the columns above the damage. The load followed this path due to the relatively large stiffness of the hat trusses-column system compared to the flexural stiffness of the floors. At a certain floor level, column splices fail due to the large tensile forces and the floors below the failed splices must redistribute their loads directly to neighboring undamaged core columns. When only eight core columns were assumed severed, the analysis indicated that the tensile forces in the columns were smaller, due to the relatively larger stiffness of the floor. These forces may still have failed the columns at the splices.
- Nonlinear analysis that included geometric nonlinearities and material nonlinearities using plastic hinges was conducted on the reduced global model of WTC 1. The model assumed the following damage to the tower: (1) due to aircraft impact, loss of columns and spandrels in the north face, and an exterior panel in the south face of the tower, as well as eight columns in the core; and (2) due to fire, loss of columns in the south face, which were shown in videos to be bowing inward a few minutes prior to collapse. The analysis indicated that after aircraft impact, the tower maintained its stability, where the highest stressed elements were the exterior columns next to the damaged area on the north face of the tower. The tower also maintained its stability after losing columns in the south wall due to fire effects with some reserve capacity left, indicating that additional loss or weakening of columns in the core, weakening of additional columns in the exterior, or additional loss of floors is needed to collapse the tower. More detailed models will account for local bucking of columns, and the failure and role of the floor system in redistributing the loads; factors that are not considered in this analysis.

# 2.4 METALLURGICAL AND MECHANICAL ANALYSIS OF STRUCTURAL STEEL (PROJECT 3)

### 2.4.1 Project Objective

Structural steel recovered from the WTC site provides information essential to understanding the events of September 11, 2001. Important data available from analysis of the steel include failure modes of the steel that provide clues to the interaction of the aircraft with the buildings and mechanical properties of the steel that assist in modeling of the buildings during impact and under the high temperatures concomitant with the fires. The steel may provide additional clues, such as information on the extent of high temperature exposure of the steel in the fires.

Thus, the objective of Project 3 is to analyze structural steel available from WTC 1, 2, and 7 for determining the metallurgical and mechanical properties and quality of the metal, weldments, and connections, and providing essential data to other investigation projects.

### 2.4.2 Project Approach

This project is divided into five substantive tasks as follows:

- Task 1–Physical Evidence. Collect and catalog the physical evidence (structural steel components and connections) and other available data, such as specifications for the steel, the location of the steel pieces within the buildings, and the specified steel properties.
- Task 2-Visual Observations. Document failure mechanisms and damage based on visual observations of recovered steel, especially for available columns, connections, and floor trusses. Photographs taken before collapse will be used to determine damage occurring to the recovered steel before collapse.
- Task 3–Mechanical Properties. Determine the metallurgical and mechanical properties of the steel, weldments, and connections, including temperature dependence of properties. The grades of steel will be identified in the columns, welds, spandrels, trusses, truss seats, and fasteners. The identification will include composition, microstructure, mechanical, and impact properties. This task will provide steel property data, including models of elevated temperature behavior for relevant steels, to estimate damage to the structural steel members from aircraft impact, evaluate structural fire response, and study the initiation of structural collapse in Project 6, Structural Fire Response and Collapse Analysis.
- Task 4–Correlation with Engineering Drawings. Correlate determined steel properties with the specified properties for construction of the buildings. The quality of the steel used in the buildings will be compared with that specified.
- Task 5–High Temperature Excursions. Analyze the steel metallographically to estimate maximum temperatures reached. It is recognized that high temperature exposure before the collapse may be difficult to distinguish from exposure during post-collapse fires.

## 2.4.3 Physical Evidence

NIST has studied steel elements from the WTC buildings and collected and analyzed documents on steel and welding specifications from the 1960s applicable to the WTC towers. This analysis has resulted in the documents described below.

### Catalog of Structural Steel

NIST has catalogued the 236 structural steel elements from the WTC buildings recovered for the investigation. These pieces represent a small fraction of the enormous amount of steel examined at the various recovery yards where the debris was sent as the WTC site was cleared. Components include full exterior column panels, core columns, portions of the floor truss members, channels used to attach the floor trusses to the interior columns, and other smaller structural components (e.g., bolts, diagonal bracing straps, aluminum facade).

NIST catalogued and documented the steel pieces, and when possible, identified markings on the steel which pinpoint the intended as-built location within the buildings. Roughly 0.25 percent to 0.5 percent of the 200,000 tons of steel used in the construction of the two towers was recovered. The recovered steel includes portions of:

- 90 exterior column panels; the as-built location of 41 distinct sections has been unambiguously identified within WTC 1 and WTC 2:
  - 26 panels from WTC 1: 22 from near the impact floors, 4 hit directly by the airplane
  - 15 panels from WTC 2: 4 from near the impact floors.
- 55 wide flange sections and built-up box sections; 12 core columns have been positively identified from WTC 1 and WTC 2, including 1 column from the impact zone of WTC 1 and 2 columns from the impact zone of WTC 2.
- 23 pieces of floor truss material from WTC 1 and WTC 2; however, the as-built location of the trusses within the buildings could not be identified.
- 25 pieces of channel sections that connected the floor trusses to the core columns in WTC 1 and WTC 2; however, the as-built location of the channels could not be identified.

The design drawings for WTC 1 and WTC 2 designate 14 different grades (or strengths) of steel for the exterior panels, four grades for the core columns, and two grades for the floor trusses. Stampings on identified perimeter and core columns indicate that the steel supplied was the appropriate strength as indicated on the design drawings, with the exception that 100 ksi plate was used for the 85 ksi and 90 ksi material called for in the design, leading to a total of 12 grades of steel in the buildings. The recovered structural elements have yielded representative samples of the following:

• All 12 grades of exterior panel material;

- Two grades of core column steel (representing 99 percent, by total number, of the columns);
   and
- Both grades for the floor truss material.

The collection of steel from the WTC towers is adequate for purposes of NIST's investigation (i.e., chemical, metallurgical, and mechanical property analyses as well as a substantial damage assessment and failure mode examination) to examine why and how WTC 1 and WTC 2 collapsed following the impact of the aircraft and ensuing fires.

More detail on the recovered steel appears in Appendix F, Inventory and Identification of Steels Recovered from WTC Buildings.

### **Contemporaneous Specifications and Other Documents**

As part of an analysis of contemporaneous (1960s era) documents, NIST has studied the building drawings to ascertain the major structural elements and grades of steel in the towers relevant to the investigation. Also, 1960s era steel and welding specifications used to construct the WTC towers have been located and analyzed. The many steels (combinations of strengths and manufacturers) that were used have been characterized based on structural engineering specifications for the buildings and manufacturer documents of the era. Appendix E, Contemporaneous Structural Steel Specifications, also describes the major structural elements in the towers relevant to the investigation.

Ten steel companies fabricated structural elements for the two towers. The floors involved in the aircraft impact and major fires contained steel from four of these companies. Laclede Steel (St. Louis, Missouri) fabricated the trusses for the floor panels that spanned the opening between the core and the perimeter columns. They used steels conforming to ASTM A36 and A242, which they made and rolled in their own mill. NIST chemical analyses and strength tests, as well as contemporaneous mill reports indicate that many of the floor truss components specified as ASTM A36 were actually fabricated with a microalloyed steel of considerably higher yield strength.

Pacific Car and Foundry (Seattle, Washington) fabricated the perimeter box column panels (generally 3 columns wide by 3 stories tall) above Floor 9. Although 14 grades of steel (36 ksi to 100 ksi yield strength) were specified in the structural steel drawings, only 12 grades were supplied due to an upgrading of two of the specified steels. Most of the steel came from Yawata Iron and Steel (now Nippon Steel) and Kawasaki Steel, although about 10 percent of the plate was produced domestically, primarily by Bethlehem Steel. Many of these steels were relatively new proprietary steels and were not covered by ASTM standards of the time. In the impact zones of the towers, the perimeter columns damaged by the aircraft were largely of three specified grades: 55 ksi, 60 ksi, and 65 ksi steels.

Stanray Pacific (Los Angeles, California) fabricated the welded core box columns (rectangular columns assembled from four steel plates) above Floor 7, primarily using steels conforming to ASTM A36. The thicker plates came from Colvilles, Ltd. (Motherwell, Scotland, now Corus Steel), while the thinner plates came from Fuji Steel (now Nippon Steel).

Montague-Betts (Lynchburg, Virginia) fabricated the rolled wide-flange core columns and beams above the Floor 9. Much of the steel for the wide-flange columns came from Yawata Iron and Steel. The rest

Montague-Betts purchased from numerous domestic suppliers. For WTC 1, the core columns damaged by impact and fire were mostly wide-flange shapes, since the highest floors of the buildings contained few box columns. In WTC 2, the damaged columns were a roughly equal mix of welded box columns and wide-flange shapes.

Details on the 1960s era documents appear in Appendix E.

### 2.4.4 Visual Observations

Visual analysis includes analysis of both photographic evidence just before the collapse and analysis of the recovered steel for clues to the performance of the steel structure throughout the event. Airplane impact damage to the towers has been characterized from enhanced precollapse photographs (Fig. 2–7). Such analyses provide input for validation of airplane impact models. In addition, these images allow investigators to determine whether damage observed in the recovered steel occurred before or after the collapse, greatly aiding the failure analyses of these pieces.




Figure 2–7. Enhanced precollapse image of the north face of WTC 1 with superimposed outline of the Boeing 767. Likely failure modes of damaged columns are indicated.

The recovered steel has been studied to determine failure modes of the various components and connections. In addition, a NIST contractor, Wiss, Janney, Elstner, has surveyed the recovered steel to characterize failure behavior.

## 2.4.5 Mechanical Properties

Mechanical tests of steel at room temperature (for baseline performance), high temperature (for strength and deformation behavior in fire conditions) and high rates of deformation (to calibrate strength enhancements occurring during airplane impact) are completed and are being analyzed. Preliminary analysis of the perimeter column and truss steel indicates that the quality and strength (relative to required minimum values) of the steel is as expected for steel of the period. Results for the core columns and connections are still being analyzed. Data are being provided to the impact damage and fire modeling teams.

Mathematical models of the stress-strain behavior of 21 steels (various grades and manufacturers) in the WTC towers have been developed and provided to contractors for use in computer models of the behavior of the buildings. The models of the steel behavior are based on the conventional room temperature tests, high strain rate tests, and high temperature characterization.

# 2.4.6 Correlation with Engineering Drawings

In order to determine if the great variety of steels were in the proper positions in the buildings, NIST has correlated stamped yield strength values (generally stamped on each plate in the perimeter panels) and the measured mechanical properties with the yield strengths on the design drawings. This correlation is largely complete, and there are no indications that any inappropriate steel was in place in the buildings.

### 2.4.7 High-Temperature Excursions

The structural steel from the impact area of the towers is being characterized to determine maximum exposure temperatures for input to Project 5. After surveying a number of possibilities, NIST developed a technique to map thermal exposure of the relevant pieces by characterization of paint condition. By this means, sections with no damage (i.e., no "mud-crack" patterns) to the paint are known to have remained below approximately 250 °C, and paint with mud-cracks, but remaining relatively intact, remained below approximately 750 °C. Above 750 °C the paint becomes powdery and flakes off. Mapping of the steel is nearly complete, and data will be supplied to Project 5.

### 2.4.8 Significant Interim Results

- 1. NIST has cataloged the 236 pieces of recovered steel (Appendix F).
- 2. Material and construction specifications of the construction period, as well as steel fabrication documents, have been located, analyzed, and documented (Appendix E).
- 3. Mechanical tests at room temperature (for baseline performance), high temperature (for strength and deformation behavior in fire conditions) and high rates of deformation (to calibrate strength enhancements occurring during airplane impact) are completed and are being analyzed.
- 4. Mathematical models of the stress-strain behavior of 29 steels (various grades and manufacturers) in the WTC towers have been developed for use in computer models of the behavior of the building during the airplane impact and during the resulting fires. The models of the steel

behavior are based on the conventional room temperature tests, high strain rate tests, high temperature characterization and literature on properties of steel produced in the era in which the WTC towers were constructed.

- 5. Airplane impact damage has been characterized from enhanced precollapse photographs and correlated with recovered steel.
- 6. Ten different steel companies fabricated structural elements for the towers, using steel supplied from at least eight different suppliers; four fabricators supplied the major structural elements of floors 9 to 107.
- 7. Documents from the era of WTC tower construction, from the steel suppliers and others, were used to estimate average yield strengths for each of the supplied steels. These strengths typically exceed the specified minimum strengths given in the engineering drawings by 5 percent to 10 percent.
- 8. In contrast to the above, extensive studies of steel from the construction period show that due to statistical variation expected in steel products, a fraction of mechanical tests would be expected to fall below specified minimums.
- Although ASTM structural steel standards have evolved since the construction of the towers, changes have been minor and do not represent changes to the basic mechanical properties of the steels.

### 2.4.9 Preliminary Findings

- 1. Analysis of recovered samples of the many grades of steel in the towers indicates that, based on stampings on the steel and mechanical tests, the correct specified grades of steel were provided for the specific fabricated elements. Furthermore, when this data is combined with pre-collapse photographic images of the five recovered WTC 1 panels in NIST's possession that were damaged by the aircraft impact, it has been shown that these particular elements contained proper steel in the precise locations as specified in the design drawings.
- 2. Metallography and mechanical property tests indicate that the strength and quality of steel in the towers was adequate, typical of the era, and likely met all qualifying test requirements.

### 2.5 INVESTIGATION OF ACTIVE FIRE PROTECTION SYSTEMS (PROJECT 4)

### 2.5.1 Project Objectives

The active fire protection systems studied in this investigation are the automatic fire sprinklers, fire detection and alarms, smoke purging, and preconnected hose lines. The automatic fire sprinkler system is the first line of defense against fires in these buildings. Water stored in the building, from public sources and even pumped from fire apparatus can be supplied through dedicated piping to the area of the fire. Also present in the buildings were preconnected hose lines connected to a water supply through standpipes located in the stairwells and other utility shafts. The standpipes provided hose connections at

each floor for the FDNY. In addition, standpipe preconnected hoses were installed for trained occupants to manually suppress fires. The heart of the fire detection system is the automatic fire alarm and emergency notification system. Occupants in the building depend on this system to detect fires and provide information for emergency evacuation. Capabilities were also designed for the ventilation system to operate in a way to purge smoke produced by fires from the building. Smoke purge was intended to be used for post-fire clean-up, but could be used during a fire event at the discretion of the FDNY.

All of the active fire protection systems provide capabilities that are important for fire control, providing information for occupants and first responders, and limiting the effects of the fire on the building and its occupants. Therefore, this project has the objectives of documenting and evaluating the performance of the installed active fire protection systems in WTC 1, 2, and 7 and assessing their role in fire control, emergency response, and the fate of occupants and responders.

### 2.5.2 Project Approach

The tasks of this project are to (1) document fire protection systems design and installation, and (2) evaluate performance without the benefit of any physical evidence from the collapsed buildings. The need to document facts associated with the installed fire protection systems was made difficult because many of the relevant documents for WTC 1, 2, and 7 were lost in the collapse of those buildings.

With the cooperation of the PANYNJ and Silverstein Properties Inc., information was obtained from other locations and from contractors, consultants, and operators. As an example, some information was obtained from the engineering offices of PANYNJ in Newark. Other written materials describing the design and operation of active fire protection systems were obtained through files maintained by contractors. Lastly, information from engineers and system operators was helpful in clarifying details of the installation and operation.

NIST investigators led three groups of fire protection systems contract experts. Each group specialized in one of the fire protection systems being investigated – fire sprinkler, fire alarm, and smoke management. The group examining the sprinkler system was also tasked with investigation of the other water-based fire suppression systems—the standpipe and preconnected hoses.

Technical assistance to NIST in the investigation of the sprinklers, standpipes and preconnected hoses was provided by Hughes Associates Inc. of Baltimore, Maryland. This group was tasked with:

- 1. Documenting the design and installation of the systems;
- 2. Documenting the design and capacity of the water supply including provisions for redundancy;
- 3. Identifying differences in the designs used in WTC 1, 2, and 7;
- 4. Documenting the normal operation and effect of the fully functional systems for fire control;
- 5. Assessing the probable performance of the systems in WTC 1 and WTC 2 on September 11, 2001; and
- 6. Assessing the installed systems with respect to present best practices.

The amount of water that the water supply and sprinkler systems were capable of delivering for a series of fire scenarios was determined using a hydraulic model of the sprinkler system and the associated water supply.

Technical assistance to NIST in the investigation of the fire alarms was provided by Rolf Jensen and Associates, Inc., of Fairfax, Virginia. This group was tasked with:

- Documenting the design and installation of the system;
- Documenting the normal operation and effect of the fully functional systems, including provisions for redundancy;
- Documenting modifications made to the fire alarm systems in WTC 1 and WTC 2 after the 1993 bombing;
- Assessing the probable performance of the systems in WTC 1 and WTC 2 on September 11, 2001; and
- Assessing the installed systems with respect to present best practices

Technical assistance to NIST in the investigation of the smoke management systems was provided by Hughes Associates, Inc., of Baltimore, Maryland. This group was tasked with:

- Documenting the design and installation of the systems;
- Describing the normal operation in fire emergencies;
- Assessing the probable performance of the systems in WTC 1 and WTC 2 on September 11, 2001; and
- Assessing the installed systems with respect to present best practices.

The NIST building airflow and contamination dispersal computer model, CONTAM, was used to evaluate the performance of several smoke management system configurations in WTC 1 and WTC 2 under specific fire scenarios.

Significant fires in WTC 1, 2, and 7 prior to September 11, 2001, were of interest to understand, in particular, how the fires were suppressed. Information was sought on all fires that activated multiple sprinklers or where hose lines were used to suppress the fires. Because the records of fire events in the buildings maintained by the PANYNJ were destroyed in the fire and collapse of WTC 1, information was collected from FDNY fire reports.

### 2.5.3 Fire History of WTC 1, 2, and 7

Fires occurred in WTC 1, 2, and 7 prior to September 11, 2001. The facts related to the performance of automatic sprinkler, manual suppression, fire detection and smoke purge systems during significant fires in the buildings after first occupancy were documented.

Extensive records of fire incidents kept in the WTC 1 offices of the PANYNJ were lost in the collapse of the building; however, FDNY maintains records of the responses to all fires. These records consist of standardized forms on which fire events are described using codes from a predefined list of descriptive phrases and categories.

The FDNY provided 397 Bureau of Operations Fire Reports and 112 Bureau of Fire Investigation Records (Fire Marshals' Reports) that served as the basis for this summary of the fire history in the WTC 1, 2, and 7. NIST reviewed these reports of fires for the period of 1970 to 2001 and fire investigation records between 1977 and 2001 for WTC 1, 2, and 7. All of these records consist of standardized forms that may be supplemented with other materials. Many were for minor fire events, such as fires that were extinguished by occupants before FDNY arrival. These were not of interest for this investigation. The records of significant fires were identified. Significant fire incidents were those involving the discharge of multiple sprinklers, use of a standpipe connected hose, or the combination of a single sprinkler discharge and a hose. As an aside, the majority of fire records for significant fires documented the performance of the detectors and sprinkler systems, but almost all reports lacked information about the performance of the smoke purge system.

Table 2–4 contains the categorization of all structural fire incidents contained in the FDNY records for WTC 1, 2, and 7 available to this Investigation. This information was obtained from 345 of the 397 Bureau of Operations Fire Reports that reported structural fire incidents. The table contains information on the category of fire incident, the time period over which the fire occurred, the number of records in that category, and a descriptive statement about the category.

Forty-seven of these cases were considered significant fires based on information about the number of sprinklers activated, and/or hose lines used to suppress the fire. Sixteen fire incidents exercised multiple sprinklers or multiple standpipes (with or without the activation of at least one sprinkler). Thirty-one fires involved the use of one standpipe line or one standpipe line and discharge of one sprinkler. These incidents are documented further in Appendix G. In addition, the appendix contains information from publicly available investigation reports of the 1975 office fire in WTC 1 and the 1993 bombing incident.

The FDNY fire reports and fire investigation records indicate that in areas protected by automatic sprinklers, no fire activated more than three sprinklers. The design area for three sprinklers is a floor area of 63 m<sup>2</sup> (675 ft<sup>2</sup>) in a light hazard occupancy, such as a high-rise office building as specified in the NFPA Standard for the Installation of Sprinkler Systems (NFPA 13).

Many of the fires that occurred were recorded as suspicious or unknown in cause, occurred during off-peak work hours, and involved materials such as trash or paper-based supplies. In cases where sprinklers were activated, the FDNY records indicated that the sprinklers either extinguished the fire completely or aided in controlling the spread.

Table 2-4. Summary of historical fires in WTC 1, 2, and 7.

WTC 1							
Category	Dates	Number	Generalization of Incidents				
No detection, no sprinkler	1980–2001	66	Unattended food/appliances, overheated elevator equipment, discarded material, welding operations, electrical failure and suspicious fires				
No detection information and no sprinklers	1970–1979	79	Trash can fires, discarded material, food on stove, electrical failure, overheated equipment				
Detection, no sprinklers	1980–2000	57	Unattended food/appliances, overheated elevator equipment, discarded material, welding operations, electrical failure				
Detection and sprinklers	1977–1999	18	Suspicious, electrical failure, discarded material				
		WTC	2				
Category	Dates	Number	Generalization of Incidents				
No detection, no sprinkler	1980–1999	37	Discarded material, welding too close, overheated equipment, suspicious, elevator motor				
No detection information and no	1975–1979	40	Discarded material, fire in office furniture, trash				
sprinklers			can fires				
sprinklers  Detection, no sprinklers	1981–1999	40	Food on stove, small elevator fire, electrical failure, suspicious, overheated equipment				
-	1981–1999 1977–2000	40	Food on stove, small elevator fire, electrical				
Detection, no sprinklers			Food on stove, small elevator fire, electrical failure, suspicious, overheated equipment  Mechanical failure, suspicious				
Detection, no sprinklers		5	Food on stove, small elevator fire, electrical failure, suspicious, overheated equipment  Mechanical failure, suspicious				
Detection, no sprinklers  Detection and sprinklers	1977–2000	5 <i>WTC</i>	Food on stove, small elevator fire, electrical failure, suspicious, overheated equipment  Mechanical failure, suspicious				
Detection, no sprinklers  Detection and sprinklers  Category  No detection, no	1977–2000  Dates	5 WTC Number	Food on stove, small elevator fire, electrical failure, suspicious, overheated equipment  Mechanical failure, suspicious  7  Generalization of Incidents				

### 2.5.4 Fire Sprinkler, Standpipe, and Preconnected Hoses

Resources used in the investigation of the sprinkler, standpipe, and preconnected hoses in WTC 1, 2, and 7 are being documented by NIST investigators and subject experts at Hughes Associates, Inc. This information will be included in the final report

The design and installation of the fire sprinkler, standpipe, and preconnected hoses are described in a report being prepared for NIST by Hughes Associates, Inc. This report will provide an analysis of the performance capabilities of the suppression systems based on hydraulic modeling of the water supply and sprinkler distribution system.

### **Preliminary Findings**

1. **Sprinkler Risers and Standpipes**. In WTC 1, 2, and 7, primary and secondary water supplies, fire pump size and locations, water storage tanks, and FDNY connections provided multiple

points of water supply redundancy. The potential for single point failure of the water supply to the fire sprinklers existed at each floor due to lack of redundancy in the sprinkler riser system that provided only one supply connection on each floor. As a result, the water supply to the sprinkler systems or a standpipe serving preconnected hoses could be interrupted by routine maintenance needs (i.e., shutdown of the riser or standpipe) or by impairment due to deliberate acts to damage the sprinkler riser or standpipe systems. While this lack of redundancy may not have had an impact on September 11, 2001 because the sprinkler system was damaged by aircraft impact, it could have made a difference in other building emergencies.

2. Water Flow Rate to Sprinklers. Aided by the results of hydraulic modeling of the sprinkler system in WTC 1 and WTC 2—undamaged by aircraft impact and fully operational—the delivered water flow rate available from the automatic sprinkler systems was found to generally exceed the minimum requirements (by a considerable margin) for a high-rise office hazard classification in accordance with NFPA 13. In a number of cases, the amount of available water flow from sprinklers on specific floors was capable of protecting higher fire hazard classes than those associated with light hazard office buildings.

### 2.5.5 Fire Alarm Systems

The WTC 7 fire alarm system was monitored by AFA Protective Systems, Inc., at a location remote from the WTC site. AFA Protective Systems furnished the record from the fire alarm system history tape to NIST for use in the Investigation.

Other resources used in the investigation of the fire alarm systems in WTC 1, 2, and 7 are being documented by NIST investigators and subject experts at Rolf Jensen and Associates, Inc. This information will be included in the final report.

The design and installation of the fire alarm systems will be described in a report being prepared for NIST by Rolf Jensen and Associates, Inc. This report will provide the analysis of performance based on the design and programming of the systems.

# WTC 7 Alarm System Monitoring Record

Although a great amount of information is normally collected and stored by any fire alarm system from fire detectors installed throughout a building, typically, and in the case of WTC 7, no specific fire information is sent to the monitoring site beyond the fact that a fire condition has been detected.

The information from the WTC 7 alarm system monitoring record for September 11, 2001, is shown in Fig. 2–8.

```
14:48:22 DYJ
09/11/01
                       4612
                              **** FULL CLEAR ****
09/11/01
        14:47:22 LATE 3923 SYSTEM TEST OVER
09/11/01
        14:47:22 COMMENT:
                             TEST: ALL
09/11/01
        14:47:21 COMMENT: LAST SET: 091101 64742
                                                                 *T
09/11/01
                       1510 CO TO CLASS E
        10:00:52
                                                     AREA:1
09/11/01
       06;47:43 COMMENT: RIC: WILLIAMS
09/11/01
        06:47:03
                 RIC
                       4210 PLACE ON TEST
                                                     CAT:11
09/11/01
        06:47:03
                 COMMENT:
                             091101 647 091101 1447
                             TEST: ALL
09/11/01
        06:47:02 COMMENT:
09/11/01 06:05:01
                 RP
                             20 TIMER TEST
```

Figure 2–8. Monitoring station history tape record for the WTC 7 fire alarm system on September 11, 2001.

The fire alarm history tape record is read from the bottom to the top. Some entries occur as the result of normal operations, and others are the result of actions taken by operators. The bottom line of the record shows that at 6:05:01 a.m. on September 11, 2001, the fire alarm system completed a normal communications check with the central monitoring station. This check is made every day.

At 6:47:02 a.m., AFA placed WTC 7 in a "TEST: ALL" condition. This is normally done in response to a request from the building manager. Ordinarily, it is requested when maintenance or other testing is being performed on the system, so that any alarms that are received from the system are considered the result of the maintenance or testing and are ignored. NIST was told by AFA that for systems placed in the TEST condition, alarm signals are not shown on the operator's display, but records of the alarm are recorded into the history file.

At 6:47:03 a.m., the record includes an explanation of the request to put the system in the TEST condition. Continuing to read from bottom to top, the date and time the system was placed in TEST is recorded. In this case it is 091101 647 (6:47 a.m., September 11, 2001), and the system will automatically go back to normal monitoring after 8 hr, a system default value, at 091101 1447 (2:47 p.m., September 11, 2001). On the next line above, "RIC" identifies the AFA operator; 4210 is a code number for the "PLACE ON TEST" message. CAT:11 indicates the authority of the person requesting the action. On the next line above, the comment entered by RIC identifies that the person who requested that the system be placed on TEST was Williams. This action appears to be common for the building alarm system. Records show that the system was placed on test condition every morning for the 7 days preceding September 11, 2001.

At 10:00:52 a.m., a fire condition [1 1510 CO TO CLASS E] was indicated in WTC 7 by sensing performed by the fire alarm system. The \*T at the right end of that record indicates that the system was in TEST at the time. The alarm record also shows that the fire condition is in AREA 1. NIST has been told by AFA that AREA 1 is not a specific area within the building, but a reference to a zone consisting of the entire building. That is to say, fires detected in any fire alarm zone in the building by the fire alarm system would result in the same AREA 1 identification at the monitoring station. The time 10:00:52 a.m.

is shortly after the collapse of WTC 2. It is unknown if this fire alarm was triggered by smoke from a fire or dust entering smoke detectors.

At 2:47:21 p.m. and 2:47:22 p.m. (14:47:21 hr and 14:47:22 hr), at the time the 8 hour "TEST: ALL" condition was set to expire, additional actions are recorded that end in an operator (DYJ) entry to "FULL CLEAR."

### **Alarm System Network Communications Paths**

During initial engineering design for the fire alarm system in WTC 1 and WTC 2, PANYNJ requested approval of the City of New York for use of fiber optic communications cable in the system. NYC Building Authorities denied the use of fiber optic cable. As a result, ordinary copper wire communication cable was specified. The copper communications cable is susceptible to electrical shorts that can prevent any communication between all of the distributed control units of the system. Fiber optic cable is not susceptible to electrical shorts. If fiber optic communications cable had been used, communications between panels where the fiber optic cable had not been severed would continue to be able to communicate with each other.

Severing either type of data communications cabling without electrical shorts would have produced the same effect on the system. The system was designed with redundant communication paths to provide Class A signaling circuits. If one communication path is served without electrical shorts, a trouble condition would be annunciated, but communications would not be impaired.

### "Standpipe Telephone" System

A dedicated communications system for emergency responders was installed in the stairwells of WTC 1 and WTC 2. To use the system, a compatible telephone handset was needed. This system was known as the "standpipe telephone" system.

### **Preliminary Findings**

- 1. **Fire Alarm Monitoring System.** The fire alarm system monitoring WTC 7 sent to the monitoring company only one signal indicating a fire condition in the building on September 11, 2001. This signal did not contain any specific information about the location of the fire within the building. From the alarm system monitor service view, the building had only one zone, "AREA 1."
- 2. Alarm System Communications Paths. The resistance to failure of the fire alarm system communications paths between the fire command station and occupied floors may have been enhanced if fiber optic communications cable had been used instead of copper lines. Extensive damage to the towers upon aircraft impact is likely to have cut and shorted the wiring of the alarm system network cables. If that occurred, communications between the distributed fire alarm panels, which are components of the integrated fire alarm system, would have been degraded and lost to certain panels depending on the location of those panels. Fiber optic cable is not susceptible to electric short-circuits and would have provided full communications with fire alarm system components, including voice communications systems, to the point where the cable was

severed. Electric shorts in the voice communications disable that communication system over the entire cable length affected by the electric short-circuit. During initial engineering design for the fire alarm system in WTC 1 and WTC 2, the PANYNJ requested, but did not receive, approval of the City of New York for use of fiber optic communications cable in the system. The NYC code required copper wiring. As a result, ordinary copper wire communication cable was specified.

3. "Standpipe Telephone" System. Some firefighters that received handsets at the command post in the lobby at WTC 1 were interviewed as part of the investigation. Every one of the firefighters interviewed indicated that they did not use the standpipe telephone communication system on September 11, 2001. Due to the loss of firefighters in WTC 2, there is no information about the use of the system in WTC 2.

## 2.5.6 Smoke Management

Resources used in the investigation of the fire alarm systems in WTC 1, 2, and 7 are being documented by NIST investigators and subject experts at NIST contractor, Hughes Associates, Inc. This information will be included in the final report.

The design and installation of the smoke management systems will be described in a report being prepared for NIST by Hughes Associates, Inc. This report will provide the analysis of performance based on the design and programming of the systems.

The smoke management systems as designed and documented in the operation manuals consisted of a smoke purge mode using the components of the main HVAC systems. The systems were intended to remove smoke and other gaseous combustion products from the fire area after a fire was extinguished. This system was to be activated "manually" at the direction of FDNY.

### **Preliminary Findings**

- 1. Smoke Management Systems Performance on September 11, 2001. Based on the information reviewed, the smoke management systems were not activated during the fires on September 11, 2001. It was determined that the likelihood of these systems being functional in WTC 1 and WTC 2 was very low due to the damage inflicted by the aircraft impacts. In addition to the significant openings created in the building envelopes, the aircraft impacts are likely to have severed major vertical shafts through which ran electrical power supply and HVAC system duct risers, thereby causing the loss of power to the smoke management system air handlers and damage to the vertical HVAC duct risers used to provide smoke management (smoke purge).
- 2. Fire/Smoke Dampers. The analysis of smoke flow in WTC 1 and WTC 2 on September 11, 2001, shows that HVAC ductwork was a major path for vertical smoke spread in the buildings. Fire dampers were installed in the systems, but not smoke dampers. Operational combined fire/smoke dampers in the HVAC ductwork on each floor would have provided a barrier to hot gas and smoke penetration into the vertical HVAC shafts in WTC 1 and WTC 2. However, smoke dampers were not available when the towers were built.

3. **Stair Pressurization Systems.** Modeling results showed that in WTC 1 and WTC 2 stair pressurization systems would have provided minimal resistance to the passage of smoke had they been installed on September 11, 2001. While the existence of such systems was known when the WTC towers were built, the alternative smoke purge system used in the WTC towers was considered to be equivalent. Multiple stair doors being open for substantial periods of time due to occupant egress, and stairway walls damaged by aircraft impact, would result in an inability to prevent smoke from entering stairwells.

# 2.6 RECONSTRUCTION OF THERMAL AND TENABILITY ENVIRONMENTS (PROJECT 5)

### 2.6.1 Project Objective

The collapse of the WTC towers resulted from a combination of aircraft impact damage and the ensuing fires. However, both the relative importance of these two factors and their interaction leading to the observed total collapse is at present unclear. It is also unresolved:

- Which structural features of the buildings were affected, and thus what location, magnitude, and duration of fire brought about the collapse, and
- Whether the nature of the fires is typical of what might be expected in common occupancies, or whether there were special features that made these fires especially severe.

These facets are even more pivotal for WTC 7, where the fires that led to the unexpected collapse followed an unknown ignition in an unknown location.

In addition to the flames and heat, the smoke from the fires plays multiple roles, for example:

- It serves as a telltale for the locating of fires, although the determination of location also requires a knowledge of smoke movement within the buildings.
- Its visual obscuration and perhaps its toxicity may have affected choices made by people as they decided direction of movement, whether to wait for rescue, etc.

Thus, Project 5 has as its objective to reconstruct, with assessed uncertainty limits, the time-evolving temperature, thermal radiation, and smoke fields in WTC 1, 2, and 7 for use in understanding the behavior and fate of occupants and responders and the structural performance of the buildings.

### 2.6.2 Project Approach

Due to the near absence of physical evidence, the recreation of the fires depends on computer modeling. NIST is redefining the state-of-the-art in fire and thermostructural modeling, since this type of reconstruction has never been done before. Fire experiments are being used to guide adaptation of existing models and develop new algorithms for them; additional experiments form the basis for validating the models.

The models will then be exercised for a range of possible initial conditions. Those simulations that agree with the photographic evidence and the eyewitness information will be accorded a higher likelihood of being correct. To the extent that simulations contradict the evidence, they will be deemed less plausible.

There is essential input that will arise from other projects, for example:

- Specifications of the liquid fuel storage systems in WTC 7 Project 1
- Degree and nature of aircraft impact damage Project 2
- Maximum temperatures experienced by the structural steel Project 3
- Performance specifications for the smoke handling system Project 4
- Extent and location of structural weakening needed for collapse to be initiated Project 6
- Eyewitness accounts of building damage and fire locations Projects 7 and 8

The interdependence with Projects 2, 6, and 7 is particularly broad, with Project 5 providing, for example:

- Establishment of the nature and precision of the information needed from the aircraft input modeling Project 2
- Descriptions of the duration and intensity of likely fires for use in assessing the possible locations of collapse initiation Project 6
- Description of fire and damage information to be requested of survivors Project 7

Project 5 is divided into the following eight tasks:

- Visual Collection and Time Line Development for WTC 1, 2, and 7. To acquire and use photographs, videos, and other relevant information to develop detailed time lines for the spread and growth of fires at the peripheries of WTC 1, 2, and 7 and to organize the information such that it can be utilized by other investigation team members. The cataloging and analysis will provide guidance on the initial conditions for modeling the fires, the rates of spread of the fires, the floors on which the structural collapses appear to have begun, etc.
- Characterization of Combustibles. To gather data on and characterize the types, mass and distribution of combustibles in the pertinent floors of WTC 1, 2, and 7 at the time of the September 11, 2001, disaster. The results are to serve as input to the overall Project 5 effort to reconstruct the thermal and tenability environment within the three buildings.
- Characterization of Partitions. To identify the location of and characterize the fire endurance properties of the internal partitions (floors, walls, and ceilings) in the pertinent floors of WTC 1, 2, and 7 at the time of the September 11, 2001, disaster. This entails obtaining existing data on the fire performance of floor, wall, ceiling systems, and complementing this with additional measurements as needed. The results will help in

- determining the potential and rates of intercompartment fire spread and also the degree to which the interior of a building was visible in the photographs and videos.
- Characterization of Structural Insulation. To determine the effective thermal properties of the structural fireproofing systems, the effect of vibration, impact, and shock on their thermal insulation performance, and whether chemical interaction between the fireproofing materials and the steel at elevated temperatures could degrade the steel and fireproofing performance during thermal insult. This will enable simulation of the temperature rise within the structural elements as a result of the changing thermal environment.
- Model Development. To upgrade the NIST computational fluid dynamic (CFD) Fire Dynamics Simulator (FDS) for its application to the reconstruction of the fires in WTC 1, 2, and 7. This will affect a pragmatic fire growth routine and also improve the efficiency of the model, enabling more extensive simulations during the timeframe of the Investigation. In addition, this task will develop a computational method for relating the turbulent fire environment to the transport of heat to and through the insulating layer to the underlying structural steel. This will enable simulation of the temperature rise and resulting loss of structural capability of the steel.
- Experiments for Model Development. To provide input parameters and guidance for the FDS combustion submodel.
- Fire Reconstruction. To reconstruct the gaseous thermal environment (radiation and temperature fields) surrounding the structural elements and in the inhabitable spaces within WTC 1, 2, and 7. Using such input information as the estimated aircraft damage from Project 2, the contents and layout of the building from the above tasks, NIST will use FDS to simulate fully involved fires in the three buildings, with and without the initial damage from the aircraft or incident debris, enabling addressing the extent to which that damage affected the thermal environment felt by the structure. Parameters in the re-creation of the fires will enable estimating the roles of jet fuel and building contents, ventilation system, compartment damage, pressurized core, and fire protection system on the growth and spread of fire. The use of statistical design for the sets of simulations will lead to identification of those input conditions to which the results are the most sensitive and those combinations of input conditions that lead to the best agreement with the photographic evidence.
- Reconstruction Validation. To generate and use experimental data for assessing the
  accuracy of the fire model prediction of thermal insult on structural members such as
  columns, trusses, beams and other support structures like those in WTC 1, 2, and 7.
   Comparison of the data from large-compartment tests of fire growth and heat transfer to steel
  specimens will establish the accuracy of FDS in simulating heat transfer and complex burning
  at a realistic scale.

### 2.6.3 Collection of Photographic Evidence

NIST has compiled an extraordinary collection of still and video images of the three buildings. These have been digitized and organized into a searchable database. The user can organize a search to view

each of the two towers from all four sides from the time of the airplane strike to the time of collapse, although there are still significant gaps in time and vantage point. The collection is less definitive for WTC 7, due mainly to the high hazard level in the vicinity following the collapses of the two towers and to obscuration of the building by other structures and the smoke cloud from the tower collapses.

To facilitate comparison of the predictions of the fire modeling (see below) with the photographic evidence, NIST has created animations of the building facades that depict the evolving breaking of windows, the emanation of smoke from the windows, the appearance of fire through the windows, and the emanation of flames out the windows.

More detail on the collection appears as Appendix H.

# 2.6.4 Data on the Building Interiors

The solicitation of information on the tenant spaces was focused on those floors of the three buildings in which physical damage was observed and those floors where fires were observed or might have existed unobserved (as shown in Table 2–5).

Table 2-3. I 10013 of Visible dallage.						
Building	Aircraft Impact Damage	Observed Fires				
1	93–99	92–99, 100, 104				
2	77–85	78–83				
7	_	7, 8, 9, 11, 12, 13, 22, 29, 30				

Table 2-5. Floors of visible damage.

#### Floor Plans

Examination of documents combined with discussions with architects, product manufacturers, occupants, and building managers indicate a general picture of the building interior. The floor slab was generally carpeted; there are some cases of raised floors and of wood- or stone-covered areas. There were glass walls at the entrances to some of the suites. For multi-tenant floors, the demising walls between the tenants were of gypsum board over steel studs and ran from the floor slab to the bottom of the slab above. Tenant space interior walls were of similar construction, but ran from the floor slab to just above the drop ceiling. Thus, the joist space was often open across a whole story or large fractions of a story. The drop ceiling systems, one for the tenant spaces and one for the core areas, were designed for the WTC.

NIST requested that tenant companies provide architectural drawings of the most recent renovation of their space. The following features are of particular importance:

- Location of walls.
  - These can act as a barrier to fire spread. In the towers, the fire resistance time of the demising and interior walls may have been comparable to the time between aircraft impact and building collapse. Even though the overall duration of the fires in WTC 7 was much longer, the walls could have limited the rate of fire spread.

- When there were walled offices at the perimeter of a floor, the interior walls block the view of the interior from the exterior. Thus, the nonobservation of fire through a particular window could indicate either the absence of a fire on that floor or the presence of a vision-obstructing wall.
- Air flow between floors. Fires need both fuel and air. To the extent that the flow of air to the fire is limited, so is the size of the fire. The direction of air access will also determine the direction(s) of fire spread. Thus, it is important to know where there were perforations, e.g., interior stairwells, air ducts, to have the most realistic sets of input conditions for the fire simulations.

NIST has obtained floor plans for a large fraction of the floors of interest in the three buildings. For the few that are missing, NIST is working with the design drawings and is estimating their similarity to the layouts on September 11, 2001, from eyewitness, tenant, and manager accounts.

#### Combustibles

While much of the public attention has been focused on the jet fuel, this was fully combusted in only a few minutes. By contrast, typical office furnishings can sustain intense fires of at least an hour's duration on a given floor. NIST has obtained generic information about the furnishings in many of the suites and specific details for a few. This information has already been of use in the design of workstation fire tests (see below). NIST is checking to identify the location and size of any unusual fuel loads, such as file rooms, film storage, etc.

In addition, NIST has obtained descriptions from the airlines of the combustible contents of the airplanes on that day. This includes the cabin materials (both installed and carried on by the passengers), aircraft components (e.g., wire insulation, flammable fluids other than the jet fuel), and the cargo bay contents. A preliminary estimate indicates that the combined mass of aircraft-borne combustibles is a considerable fraction of the building combustibles in the impact zone.

For WTC 7, NIST is aware of two special sources of combustible fluids. Rolf Jensen and Associates, Inc., a NIST contractor, is gathering data on the fuel tanks and distribution lines for the emergency generators in WTC 7. NIST has obtained information on the magnitude of the volume of the transformer fluids located in the power substation in WTC 7.

### 2.6.5 Insulation of Structural Members

The required fire resistance ratings of the structural members in the three buildings were obtained by gypsum framing of some columns or the use of spray-applied fireproofing on other columns and web joists. The architectural drawings provide definition of the former. Working from documents and discussions with engineers, NIST has identified the various spray-applied fireproofing materials and where each was used, as shown in Table 2–6. For the exterior columns in the towers, both Vermiculite plaster and BlazeShield DC/F were used. NIST is still investigating the specific locations for each.

Table 2–6. Types and locations of spray-applied fireproofing on fire floors.

		Locations			
Building	Fireproofing Material	Interior Columns	Floor Systems	Exterior Columns	
WTC 1	BlazeShield II		Floors 92 to 100, 102		
	BlazeShield DC/F	Yes	Remaining floors		
	Vermiculite plaster and BlazeShield DC/F			Yes	
WTC 2	Vermiculite plaster and BlazeShield DC/F	Yes	Yes	Yes	
WTC 7	Monokote ML-5	Yes	Yes	Yes	

The ability of the fireproofing to delay the rise of temperature in the protected structural steel depends on:

- The thermophysical properties of the insulation material. NIST has obtained samples of the three types of spray-applied insulation and four types of gypsum wallboard and has sent them to testing laboratories for determination of their thermal conductivity, density, and heat capacity, all as a function of temperature from ambient. The spray-applied material data will be from 25 °C to 1,200 °C; the wallboard data will be from 25 °C to 600 °C.
- The thickness of the insulation. The gypsum wallboard thickness is described in the architectural drawings. As documented in the May 2003 Progress Report, NIST has traced the evolution of the intended thickness of the spray-applied material. NIST has evaluated the variation in the actual thickness of the fireproofing in the WTC towers. Appendix I presents the results of that evaluation.
- Any damage to the layer during construction or refitting of the building. Damage from the impact or shock of the incident airplane (WTC 1 and WTC 2). NIST will obtain estimates of the impact intensity from ARA, which is the NIST contractor modeling the aircraft impact under Project 2. Using both standard and custom measurement methods, NIST is determining the cohesive properties (shear strength and tensile strength) to steel of the two types of spray-applied insulation used in WTC 1 and WTC 2. NIST is also developing models to predict dislodgement of the insulation.
- Damage from distortion of the WTC 1 and WTC 2 structures from the impact or the fires.
- Damage to the insulation in WTC 7 from incident debris from the collapse of the towers.

Prior to this Investigation, there was no computational method for modeling in three dimensions the effect of a fire on structural assemblies, that is, modeling the absorbance of incident heat from a turbulent fire by an insulating surface, the transport of heat through the insulating layer, and the distribution of heat throughout the steel structure. This is in large part because the turbulent fire is characterized by short time steps and large computational cell size, while the structural member is characterized by longer time steps (slower changes in temperature) and smaller computational cell size.

NIST has developed a tool to do just this, the Fire-Structure Interface (FSI), for the first time linking FDS with ANSYS (a finite element, FE, thermostructural model). Of particular importance is the relationship between the thickness of the insulation and the time for the underlying steel to reach a temperature at which the steel strength is compromised. Variations in thickness could be random in nature or as stark as bare spots.

The first computational runs were for a column as heavy as the thickest core column on the floors of impact in WTC 1. For each of three cases, a sequence of portraits of the temperature distribution in the steel was generated throughout an exposure to a uniform external temperature of 1,100 °C. From these depictions, the following times were determined for when the steel temperature reached 600 °C, a temperature near which significant compromising of the steel's structural properties would ensue:

- Insulation with the (estimated) properties of BlazeShield applied to a thickness of 13 mm. The time to reach 600 °C was over 10 h.
- A 20 percent reduction in the total mass of insulation, with the loss of thickness being varied randomly. The time to reach 600 °C was about 6 h.
- All insulation removed from one face of the column. The time to reach 600 °C was about 12 min.

In a second set of calculations, the same material was applied to a bar 25 mm  $\times$  25 mm  $\times$  1,500 mm. A 25 mm notch (to bare metal) of insulation was removed from the midpoint of the bar. Upon exposure to the same thermal environment, the temperature of the steel reached 600 °C along its full length in a matter of minutes.

A further description of the interface and sample calculations appears in Appendix J. The preliminary indications are that, in the future predictions of the impact of the WTC fires on structural members, NIST should expect the results to be sensitive to small gaps in the thickness of the insulation. In other words, small areas of thin or missing insulation can lead to accelerated heating, and this effect could be felt well away from the susceptible sites.

### 2.6.6 Modeling the Fires

In simulating the fires, NIST will be examining the effects of uncertainty in knowing the initial conditions of the fire and the building. Thus, it is critical that the accuracy of the fire model itself be established so that the uncertainty in the model's predictions is small compared to the effects caused by the differences in the initial conditions.

As a first step, certain enhancements to FDS were implemented:

Realistic state relation curves for underventilated fire scenarios. The prior computational
code used ideal state relations for its combustion routine, i.e., user-prescribed values for the
combustion efficiency that did not change as the ventilation within the fire compartments
evolved.

- The combustion module was enhanced to enable the inclusion of charring materials, such as those that comprise much of the office furniture.
- Computational code enhancements to enable time-efficient computations. Multiblock gridding now enables needed dimensional resolution in the vicinity of the structural components. The FDS code was also re-written for parallel processing.
- Fire spread. Each combustible is characterized by a heat of gasification, with the surface irradiance calculated from the thermal radiation field generated by existing fire. When the mixture fractions in two adjacent computational cells straddle the stoichiometric value, the flame then extends to the interface between the cells.
- Enhanced visualization. Smokeview has been modified to handle the extremely large data sets that will be generated in these simulations.

A first set of experiments was conducted in the NIST Large-scale Fire Laboratory to assess the accuracy with which FDS predicts the thermal environment in a burning compartment and to establish a data set to validate the prediction of the temperature rise of structural steel elements using FSI. Within a large test compartment, assorted steel members were exposed to controlled fires of varying heat release rate and radiative intensity. The steel members were bare or coated with spray-applied fireproofing of two thicknesses. The thermal profile of the fire was measured at multiple locations within the compartment. Temperatures were also recorded at multiple locations on the surfaces of the steel, the insulation, and the compartment. Prior to each test, a prediction of the thermal environment in the compartment was determined using FDS. Following the tests, the prediction and experimental results were compared.

Much of the combustible material on the fire floors of the WTC buildings consisted of employee workstations. Each such space was a combination of desk space, generally made of fiberboard with a laminated finish; file cabinets; carpet; chair; computer; paper; etc. NIST conducted a set of fire tests of a generic workstation in our Large Fire Laboratory. A single unit was burned under a large hood with a soffitted ceiling. Ignition was by a 2 MW spray burner, simulating an already burning adjacent workstation. Test variables included the combustible mass, the presence of jet fuel, and the presence of inert material (simulating fallen ceiling tiles or wall fragments). Gasification data for the combustible was generated using a Cone Calorimeter. These data plus the geometry of the workstation were used as input to the fire model. The intent was to use the experiments to identify any needed changes in the combustion algorithms. In fact, little adjustment was needed. These tests and their analyses are detailed in Appendix J.

A third set of tests was conducted to determine the accuracy of the FDS under conditions simulating a portion of a representative floor of the WTC towers. Thus, the predictions of the outcome of the tests were performed prior to the experiments. Three workstations were situated in a large compartment. Two were contiguous, the third was across an aisle. The open end of the compartment had windows of aspect ratio similar to those in the towers. The test variables included the presence of jet fuel, the presence of inert material, the location of the ignition burner (at or away from the windows), and the extent to which the workstations had been reduced to rubble. The analysis of the results is under way, but preliminary indications are that the model predictions closely resembled the test results.

Additional information on the three sets of experiments appears in Appendix J. Full reports on the first two sets of experiments are expected in the coming months.

### 2.6.7 Preliminary Findings

To date, the calculations and analyses have led to several interim findings that will guide the reconstruction of the fires in the three WTC buildings:

### **Observed Fires**

- 1. Despite the airplane striking the center of the north face of WTC 1, the resulting fires are not symmetric about the centerline of the building. After the initial fireballs, the flames damped considerably. The early fire growth was on the north face, the center of the east face and the west side of the south face. On some floors, there was continuous spread; in some instances sudden, noncontiguous fires appeared.
- 2. The damage and initial fires in WTC 2 were highly asymmetric, as the airplane struck off center to the east. Burning debris piles of long duration were observed at the northeast corner of some floors. In general, the fires spread less actively than in WTC 1, but there were sudden fires here as well. There was visual evidence of collapsed floors.

### **Building Interiors**

- 1. The view through many windows was blocked by interior walls.
- 2. The mass of aircraft solid combustibles was significant relative to the mass of the building combustibles in the impact zone.
- 3. In laboratory experiments, impulses like those estimated from the aircraft caused serious damage to the ceilings. This is consistent with the accounts of survivors from floors below the impact zone. This damage enabled "unabated" heat transport over the walls and to the joists. Small areas of thin or missing insulation can lead to accelerated heating over much larger lengths of steel.

### **Combustion Modeling**

- 1. FDS is a useful tool to recreate the burning of the complex arrays of combustibles that existed in the WTC buildings, provided that the initial damage conditions and combustible descriptions are accurate.
- FSI is a tractable construct for linking the output of a computational fluid dynamic model of the fire-generated thermal environment in the building compartments to a FEM of the building structure.

# 2.7 STRUCTURAL FIRE RESPONSE AND COLLAPSE ANALYSIS (PROJECT 6)

### 2.7.1 Project Objective

Both the north and south towers, WTC 1 and WTC 2, were severely damaged by the impact of Boeing 767 aircraft, yet they remained standing for some time. The ensuing fires were observed to move through both buildings until their eventual collapse. The extent and relative importance of the structural damage caused by the aircraft impact, and subsequent weakening due to the fires, is still being investigated. WTC 7 was reported to be damaged by falling debris from the collapse of WTC 1. The fires in WTC 7 that burned for much of the day appeared to play a key role in the building collapse. Project 6 addresses the first primary objective of the NIST-led technical investigation of the WTC disaster: to determine why and how WTC 1 and WTC 2 collapsed following the initial impacts of the aircraft and why and how WTC 7 collapsed. Specifically, the objective of this Project is to determine the response of structural components and systems to the impact damage and fire environment in WTC 1, 2, and 7, and to identify probable structural collapse mechanisms.

### 2.7.2 Project Approach

Three steps are required to determine the response of structural components and systems to fire conditions. First, the thermal environment (radiation flux and temperature fields) for the floors involved in fire are determined using computational fluid dynamics calculations. The predicted upper layer gas temperatures vary both spatially and temporally. Next, transient thermal analysis is used to predict the time-temperature relationship for the structural components and systems for bare and fireproofed steel conditions. Finally, the time-dependent structural response of the components and systems to the estimated service loads and elevated temperatures is computed using thermal-mechanical FEA.

Project 6 relies heavily on information provided by other projects, specifically:

- Reference structural models of typical floor and exterior wall subsystems of each WTC 1 and WTC 2 tower (Project 2)
- Extent of aircraft damage to WTC 1 and WTC 2 (Project 2)
- Mechanical properties of the steels, welds, and bolts used in the construction of the towers, including elastic, plastic, and creep properties from 20 °C to 700 °C (Project 3)
- Thermal properties of spray-on fire resistant materials (SFRM) (Project 5)
- Temperature time-histories for various components, sub-systems and systems for both standard fires (e.g., ASTM E 119) and real fires based on fire dynamics simulations (Project 5).

This project is divided into several tasks as follows:

• Evaluate the structural response of floor and column subsystems under fire conditions.

- Evaluate the response of the WTC towers under fire conditions, both with and without aircraft impact damage.
- Identify and evaluate candidate hypotheses for initiation and propagation of collapse, and estimate the uncertainty for probable collapse initiation and propagation mechanisms.
- Conduct tests of structural components and systems under fire conditions.
- Report on the performance of open-web steel trussed joist systems in fire.
- Analyze the response of WTC Building 7 under fire conditions.

Work completed to date on the above tasks is summarized in the following sections.

# 2.7.3 Fireproofing of WTC Towers

In May 2003, NIST issued an interim report on the Procedures and Practices Used for Passive Fire Protection of the Floor System of the World Trade Center Tower Structures as Section 3.3 of the May 2003 Progress Report. The report summarized factual data contained in documents provided to NIST by the PANYNJ and its contractors and consultants; by Laclede Steel Company, the firm that supplied the floor trusses for the WTC towers; and by United States Mineral Products Co. (USM) doing business as Isolatek International, the manufacturer of the fireproofing material.

The report discusses the applicable building codes and building classification system, which dictates the fire rating required for structural members and assemblies. The structural system for the WTC towers was constructed predominantly with steel, which, in general, requires protection from fire to maintain its strength and stiffness. Available information on the spray-on fireproofing and the procedures and practices used in its selection and application is presented. Additionally, the report discusses the procedures and practices used to determine whether tests were needed to evaluate the fire endurance of the structural elements, and it presents the results from one such test.

In May 1963, the Port Authority instructed its consulting engineers and architects to comply with the NYC Building Code for the design and construction of the WTC towers. Because the NYC Building Code was being revised during this period, the plans for fire protection of the structural steel underwent concurrent modification. While available records suggest that the fireproofing of the columns, beams, and spandrels was not a subject of concern, fireproofing of the floor bar joists was the focus of continuous reassessment and revision.

A few of the more significant interim findings are:

• The WTC towers were identified as Occupancy Group E – Business, and classified as Construction Class IB in accordance with the 1968 NYC Building Code. This classification required that the columns and floor systems of the towers have a 3 h and 2 h fire endurance, respectively.

- The steel trusses that supported the floors of WTC 1 and WTC 2 were fireproofed with specified 1/2 in. of spray-on fire-protection although the technical basis for the selection of fireproofing material and its thickness are not known.
- In 1999, a decision was made to begin upgrading the fireproofing to a specified 1 1/2 in. thickness as tenant spaces became unoccupied. In general, the floor systems in WTC 1 subject to impact and fire conditions had been upgraded; the floors in WTC 2 subject to impact and fire conditions had not been upgraded.
- The fire protection of a truss-supported floor system by directly applying spray-on fireproofing to the steel trusses was innovative at the time the WTC towers were designed and constructed and, while the benefits of conducting a full-scale fire endurance test were recognized by the building designers, no tests were conducted on the floor system used in the WTC towers to establish a fire endurance rating.

The specified material and thickness of SFRM at the time of construction are as given in Table 2–7.

Table 2-7. Specified passive fire protection

Table 2-7. Specified passive fire protection.								
Structural Component	Member Size	Location	Material	Thickness (in.)				
Floor trusses	All	All	Cafco DC/F	1/2				
Interior columns	< 14WF228	All	Cafco DC/F	2 3/16				
	≥ 14WF228	All	Cafco DC/F	1 3/16				
Exterior columns	"Heavy"	Exterior faces	Cafco DC/F	1 3/16				
	"Heavy"	Interior faces	Vermiculite aggregate	7/8				
Spandrel beams	All	Exterior face	Cafco DC/F	1/2				
	All	Interior face	Vermiculite aggregate	1/2				

# 2.7.4 Response of WTC 1 and WTC 2 Floor and Column Systems under Fire Conditions

The detailed component and subsystem models will provide guidance for the analysis of the larger, global analysis of each WTC tower under damage and fire conditions. To determine the structural response of components and subsystems under fire conditions requires the development of nonlinear structural models that account for gravity (service) and thermal loads, temperature dependent material properties, and nonlinear structural behavior, such as plastification and large deflection effects, including instability. These nonlinear structural models are then subjected to thermal-mechanical analysis to determine the time-dependent structural response to the estimated service and fire loads. The commercially available FEA code, ANSYS (version 8.0), is being used for the thermal and mechanical analyses.

The analytical work is being conducted with the assistance of Simpson Gumpertz & Heger Inc. under a contract from NIST and includes the following tasks:

- Task 1. Component, Connection, and Subsystem Structural Analysis
- Task 2. Global Analysis of the WTC Towers Response to Fire Without Impact Damage
- Task 3. Global Analysis of the WTC Towers Response to Fire With Impact Damage

The scope of work under Task 1 includes: (1) the development and validation of ANSYS models of the full floor and exterior wall subsystems, (2) evaluation of structural responses under dead and live loads and elevated structural temperatures, (3) identification of failure modes and failure sequences, and the associated temperatures and times-to-failure, and (4) identification of simplifications for the global models and analyses.

Selected technical results and findings for the typical floor system and its components are presented in the following sections. More detailed coverage is given in Appendix K, Interim Report on Structural Fire Response and Collapse Analysis. A simplified approach to the analysis of the WTC truss-framed floor system response to fire is presented in Appendix M, Interim Report on 2-D Analysis of WTC Towers Under Gravity Load and Fire.

### **Structural Models and Analyses**

Structural FEMs of components and subsystems have been developed for the following:

- Shear connector between the truss and concrete slab, referred to as a knuckle, shown in Figure 2–9
- Truss-to-column bearing seats
- Truss section, including composite floor slab, knuckles, and truss seat connections to columns
- Single-story exterior column for a 9-story height




Figure 2–9. Features of truss model.

- Exterior wall subsystem consisting of a 3-by-3 panel section of the exterior wall, where a panel is 3 columns wide and 3 stories long
- Full floor subsystem including the concrete slab, truss seat connections to columns, and core floor area

The truss section model (see Figs. 2–9 and 2–10) includes the following:

- Temperature-dependent elastic material properties for both steel and concrete
- Temperature-dependent steel plasticity




Figure 2–10. Truss model.

- Buckling of truss members
- Failure of knuckle leading to loss of composite action
- Failure of studs on the strap
- Failure of stud between the spandrel and the concrete slab
- Failure of truss resistance welds between the web diagonals and the chords
- Failure of the exterior and interior truss seats

The full floor subsystem model includes the following:

- The main trusses and bridging trusses
- Concrete slab with metal deck
- Strap and seated connections to columns

• Restraint provided by interior and exterior columns

The model was developed by translating a SAP2000 full floor model developed under Project 2 into ANSYS format and validating the analysis results against the SAP2000 model for design loads. A corner of the full floor model is shown in Fig. 2–11.




Figure 2–11. Converted ANSYS model of floor 96.

### **Summary of Technical Results**

### Capacity of Truss-to-Column Connections

The horizontal and vertical load capacities of the twelve truss-to-column connection configurations on floor 96 have been calculated. These calculated capacities were used to develop simplified models of the connection behavior for use in the floor and exterior wall subsystem analyses. As an illustration, Fig. 2–12 shows a seated connection of the floor truss to the exterior wall of the tower (spandrel plate). The connection is designed to carry vertical floor loads and horizontal loads that are at least 2 percent of the column design load. These connections may be subjected to large horizontal forces, and the capacity of the exterior truss connection under such circumstances must be ascertained.




Figure 2–12. Exterior connection of the floor truss to the spandrel plate.

The failure modes considered for the truss-to-column connections are: (1) failure of the groove weld between gusset plate and spandrel, (2) failure of the fillet weld between the gusset plate and the truss top chord, (3) tensile failure of the gusset plate, (4) bolt shearing off, (5) bolt bearing, (6) bolt tear-out, and (7) block shear failure. Possible failure sequences are illustrated in Fig. 2–13. Of the seven exterior connections types that were analyzed, path A is the failure sequence most frequently followed, which is described as follows: first the gusset plate yields across its section and then fractures, followed by truss sagging and deformation and the bolts slipping until they bear against the edge of the slotted hole, then the bolt shears off, and finally the truss walks off the seat. The travel distance for the truss to walk-off of the seat is 4 5/8 in. Sequence (A) and typical tensile force resistance for an exterior seat is shown in Fig. 2–14.




Figure 2–13. Failure sequence of exterior seats for tensile forces.




Figure 2–14. Typical tensile force resistance of exterior seat connection.

### Knuckle Analysis

The knuckle is a shear connector formed by the extension of the truss diagonals into the concrete slab. Composite action is developed due to the shear transfer between the knuckle and the concrete slab in both the longitudinal and transverse truss directions. The objective of the knuckle analysis is to predict its shear capacity when the truss and concrete deck act compositely and to develop a simplified model of the knuckle behavior for the full floor subsystem model. FEAs have been conducted and calibrated against tests of both longitudinal and transverse loading conditions that were conducted by Laclede Steel in 1967.

Figure 2–15 shows the FEM of the longitudinally loaded knuckle, representing one quarter of the knuckle test specimen. The ANSYS LS-DYNA program, which is part of the ANSYS software package for explicit nonlinear structural analysis, was used for the analysis of the knuckle tests as it had a concrete material model for nonlinear behavior. Solid steel elements were used for the knuckle and channel members and the Psuedo Tensor material model in LS-DYNA was used for the concrete. The knuckle-to-concrete interface was modeled as a bonded or no-friction contact. The finite-element analysis results of the knuckle capacity depended on the steel-concrete interface assumption of bonded or no-friction contact.




Figure 2–15. Finite element model of transversely loaded knuckle.

### Truss Analysis

A typical long-span truss, designated as C32T1, is modeled to study its response to failure when subjected to dead and live loads and thermal loads. The model includes the following:

- One truss of the pair of trusses at column line 143 in floor 96 of WTC1,
- Two exterior columns (columns 143 and 144) with half the area and bending properties (see plan view of Fig. 2–10), and a length of 24 ft (12 ft above and below the floor level),
- The portion of the spandrel between the two exterior columns,
- The portion of the slab (40 in. wide) between the two exterior columns,
- One strap anchor that is attached to the truss top chord, concrete slab and the adjacent exterior column (Column 144), and
- Exterior and interior seats, and the top plate at the exterior end.

A typical slab section consists of 4 in. thick lightweight concrete on 22 gauge metal deck and has two layers of welded wire fabric. An equivalent thickness of 4.35 in. is used as the slab thickness to account for the fluted metal deck profile. The metal deck and the welded wire fabric are not included in the truss model. Steel bar joist trusses support the concrete slab and act compositely with it. The chords of the trusses consist of double angles while the web members are round bars.

The truss and the columns are modeled with temperature-dependent elastic and plastic material properties. The concrete slab is modeled with shell elements. The nodes of the concrete slab are located at the neutral plane of the concrete slab with an offset relative to the nodes of the top chords. A low tensile yield stress is used to simulate concrete cracking. At knuckle locations, the top chord elements and the elements representing the concrete slab are connected by control elements with capacities determined

from the knuckle analysis. Studs on the strap between the top chord and column are also modeled by control elements that connect the strap to the slab. The exterior and core truss seats are modeled by a combination of control elements and link elements, which can have temperature-dependent capacities determined from the truss seat analysis. The interior column is modeled as a fixed support for the interior truss connection, allowing no lateral displacements at the floor level, as the column was braced by the core framing.

Loading consists of gravity dead and live loads and temperature time-histories for all steel members, including the truss seats. The gravity loads include weight of the structure, superimposed dead load (including nonstructural dead loads due to architectural items and fixed service equipment), and a service live load equal to 25 percent of design live load. The steel and concrete temperatures were subjected to a uniform heating condition by ramping to a maximum temperature over 1,800 s and then holding the maximum temperatures for another 1,800 s. The steel temperature increased from 20 °C to 700 °C; the bottom surface of the slab increased from 20 °C to 700 °C, and the top surface of the slab increased from 20 °C to 300 °C. This thermal load creates a linear temperature gradient through the slab from 300 °C at the top surface to 700 °C at the bottom surface of the slab. Elevated temperatures are not applied to the columns.

The truss model can capture the following:

- Temperature-dependent elastic material properties for both steel and concrete
- Temperature-dependent steel plasticity
- Buckling of truss members
- Failure of knuckle loss of composite action
- Failure of knuckle causing loss of composite action
- Failure of studs on the strap
- Failure of stud between the spandrel and the concrete slab
- Failure of the exterior and interior truss seats

Figure 2–16 shows that the top chords of the truss yield in compression beyond 300 °C (for clarity, the concrete floor slab is not shown). This is due to a significant difference of coefficients of thermal expansion (CTE) between concrete and steel. At 500 °C, the CTE of steel is twice that of light-weight concrete. Bottom chords remain in the elastic range throughout the thermal loading. Web diagonal buckling starts around 350 °C and, as seen in the figure, some diagonals are bent significantly in the plane of the truss by high axial force and end moments.




Figure 2–16. Finite element solution for floor truss under gravity and temperature loads.

## **Preliminary Findings**

Preliminary findings are described here for floor truss connection capacities, knuckle capacities, and floor truss response to the uniform heating condition.

#### Floor Truss Connection Capacities

Capacities of the interior and exterior floor truss connections, for both vertical (gravity) and horizontal forces (tension and compression), have been computed for the variety of connection types found on floor 96 of WTC 1. In all cases, the sequences of failures of the connection components have been taken into account, as illustrated in Fig. 2–13, for the exterior seated connection under horizontal (tension) force. Capacities have been computed as a function of temperature for the applicable plate, weld, or bolt properties. It should be noted that while the computed vertical and horizontal capacities are primarily due to the loads they must support, construction-related decisions may have increased the capacity. For example, an available bolt or steel section size or a minimum allowable weld thickness may provide greater capacity than that required for design loads.

Failure mode of the interior truss seat for vertical force is the fracture of the fillet welds at the seat-to-channel beam connection. Failure mode of the exterior truss seat for vertical force is fracture of the fillet welds at the stand-off-to-spandrel connection. Preliminary findings of connection capacities for vertical bearing forces at room temperature (20 °C), 400 °C, 600 °C, and 700 °C are summarized in Fig. 2–17.

Similarly, connection capacities for horizontal tensile forces at the same temperatures are shown in Fig. 2–18. For interior truss seat connections, the shear strength of the two bolts controls the horizontal tensile capacity. The connection capacity of exterior truss seats that follow failure sequence (A), as shown in Fig. 2–13, equals the failure load for the tensile capacity of the gusset plate. Note that the strength of the truss seat #1013 increases by approximately 38 percent at a temperature of 100 °C. For temperatures less than 100 °C, the horizontal capacity is controlled by the gusset fillet weld strength, and for temperatures above 100 °C, the bolt bears against the edge of the slotted hole and increases the capacity of the connection.




Figure 2–17. Truss seat capacity for vertical forces.




Figure 2–18. Truss seat capacity for horizontal forces.

#### Knuckle Analysis

FEA results of the knuckle under longitudinal loading are shown in Fig. 2–19. Displacement results shown in Fig. 2–20 indicate a significant dependence on the characteristic of the interface between the steel and concrete. Results show that each knuckle has a capacity in the range of 15 klb to 35 klb, depending on the steel-to-concrete interface assumption. Results of longitudinal shear tests conducted by Laclede Steel in 1967, using normal weight concrete with an average compressive strength of 3,707 psi, indicate an average shear capacity of approximately 28.3 klb per knuckle. After adjusting for the strength of in-place light-weight concrete of 4,100 psi (i.e., multiplying 28.3 klb by the ratio of 4,100 to 3,707 psi), the longitudinal shear capacity of the knuckle is approximately 31 klb per knuckle. This is consistent with the finite element solution for the fully bonded case shown in Figure 2–21 (note results are for two knuckles). A shear capacity of approximately 30 klb per knuckle is used for subsequent analyses of the floor truss.




Figure 2–19. Compressive stress in longitudinal shear.




Figure 2–20. Shear force versus displacement for two knuckles under longitudinal shear.

## Truss Analysis

The floor truss analysis was carried out dynamically with 5 percent Rayleigh damping and a temperature ramp set to 1.0 s. The floor slab had only gravity loads applied; no other loads related to floor diaphragm action were included. The analysis of truss behavior under the gravity plus thermal loading proceeded to a temperature of T=663 °C. Figure 2–20 shows the horizontal displacement of the column and the vertical midspan displacement of the truss. A positive horizontal displacement indicates that the exterior columns are pushed out, and a negative vertical displacement indicates that the truss is deflected downward.




Figure 2–21. Floor truss response due to gravity load and uniform heating.

As the truss and floor slab heat up, the column is pushed outward by thermal expansion. The trust top chord begins to yield in compression around 300 °C due to the difference in coefficient of thermal expansion between steel and lightweight concrete. At approximately 340 °C, web diagonals begin to buckle and the horizontal displacement at the exterior column reverses and begins to decrease. At 400 °C, knuckles start to fail sequentially from both interior and exterior supports toward the center. With the loss of composite action, the floor begins to sag at an increasing rate. Eventually, at about 500 °C, with the truss sagging almost 20 in., the bolts at the interior connection are found to shear. At 560 °C, the exterior columns begin to displace inward, and the truss begins to act as a catenary. At 650 °C, the truss walks off the interior seat while the interior end of slab remains intact and continues to carry vertical load. For the truss to walk off the interior seat, the truss must shorten by 4 in. This shortening is caused mainly by the significant plastic deformation of the top chord of the truss (Fig. 2–14), resulting from differences in the thermal expansion of the top chord relative to the slab and the failure of the first two knuckles near the interior seat. At roughly 660 °C, the gusset plate fracture at the exterior end which precipitates vertical failure of the exterior seated connection.

The results for the additional debris weight show that the knuckles start failing when 2.4 times dead load is applied. Most knuckles fail before 3.0 times dead load. After the knuckle failure, the truss loses composite action between the truss and the concrete slab, and the vertical displacement increases significantly. As a result, the horizontal reaction force increases.

Models of the truss, including knuckles with temperature-dependent capacities, diagonal weld failure, steel creep strains, and concrete cracking and crushing, are under study.

#### **Summary of Preliminary Findings**

Preliminary findings for a single truss and its seat connections and knuckles subject to service load conditions, uniformly increasing elevated temperatures in the steel, and an increasing temperature gradient in the concrete slab, can be summarized as follows:

- The floor truss first experiences increasing vertical deflections at midspan as it pushes outward and exerts a compressive lateral load on the exterior column. The exterior column begins to displace outward at the floor connection.
- As web diagonals begin to buckle at 340 °C, the midspan deflection continue to increase but the horizontal displacement of the exterior column begins to decrease. The maximum horizontal displacement of the exterior column is approximately 0.7 in. when the diagonals begin to buckle. The interior column is assumed to have no lateral displacements at the floor level, as it was braced by the core framing.
- Knuckles at each end of the truss begin to fail as the steel and bottom surface of the slab
  temperatures reach 400 °C, with knuckle failures moving progressively inward from the truss
  ends. The failure of web diagonals and knuckles at the ends of the truss reduce the flexural
  rigidity of the floor truss at the ends, further increasing the floor sag and decreasing the lateral
  outward force exerted on the columns.
- The truss bearing angle slips until the bolt is bearing against the edge of the slotted hole. The bolt shears off at the interior seat connection at approximately 500 °C. The floor truss sag increases to 20 in. when the bolt fails.
- The interior end of the reinforced slab continues to carry vertical loads as the truss bearing angle continues to slip. At 560 °C, the exterior column begins to be displaced inward as the floor truss continues to sag and exert vertical and horizontal tensile loads.
- At 650 °C, the truss begins to walk off the interior seat, followed by fracture of the gusset plate at the exterior connection at 660 °C. Fracture of the gusset plate precipitates weld failure of the exterior seat connection resulting in complete loss of vertical support of the truss.
- The truss model, with knuckle and seat connections, includes all potential failure modes that
  may occur under loading and thermal conditions, though the actual sequence of failure may
  differ under other loading and fire conditions.

## 2.7.5 Standard Fire Endurance Tests of Floor System

Standard Fire Tests of the steel truss-supported concrete slab floor system used in the WTC towers are being conducted by UL. The results of the testing will provide the fire endurance ratings of typical floor construction to evaluate three primary factors: (1) test scale, (2) fireproofing thickness, and (3) thermal restraint. Four ASTM E 119 Standard Fire Tests of the WTC floor construction will be performed as follows:

- 17 ft span assembly, thermally restrained, SFRM thickness of 1/2 in.
- 17 ft span assembly, thermally restrained, SFRM thickness of 3/4 in.
- 35 ft span assembly, thermally restrained, SFRM thickness of 3/4 in.

• 35 ft span assembly, thermally unrestrained, SFRM thickness of 3/4 in.

The first test represents current U.S. practice for establishing a fire endurance rating of a building construction. The test assembly, fabricated to meet the design of the World Trade Center steel joist-supported floor system, has a span of 17 ft. This span is typical of the floor assembly test furnaces used by the U.S. testing laboratories that routinely conduct the ASTM E 119 test for the construction industry. As is common practice, the floor assembly will be tested in the thermally restrained condition. This test will be conducted at UL's Northbrook, Illinois, fire test facility. A second test will be identical except for the thickness of SFRM.

The third and forth tests will be at twice the scale of the first two tests, with a span of 35 ft. This span represents a full-scale assembly of the 35 ft floor panel of the WTC floor system. The floor assembly for the third test will be thermally restrained as in the first two tests, thereby allowing direct comparison for the determination of the effect of test scale on fire endurance rating. The fourth test will be conducted in the thermally unrestrained support condition, which will allow direct comparison of the effect of thermal restraint on the fire endurance rating. The third and fourth tests will be conducted at the UL Canada fire test facility near Toronto.

In all tests, individual structural members of the steel trusses with varying thickness of SFRM will be exposed to the standard fire environment, and temperatures will be recorded. This will allow comparison of results for various amounts of fireproofing based on the end point criteria for steel temperatures.

The test specimens have been designed and fabricated to duplicate as closely as possible the actual floor system in the WTC towers. Laclede Steel shop drawings were used to ensure the specimens were dimensionally accurate. Properties of the constituent materials and components have been duplicated as closely as possible, including the steel angles and rods that make up the floor trusses, concrete (lightweight aggregate, air entrainment, etc.), metal deck, welded wire fabric, reinforcing steel, shop primer, and Cafco DC/F SFRM. NIST has overseen fabrication of the steel trusses, assembly of test specimens, and casting of the concrete slab and test cylinders. NIST will continue oversight of the installation of instrumentation and application of SFRM.

The test assemblies have been fabricated as shown in Fig. 2–22, and at this time, the concrete floor slabs are drying to the ASTM E 119 specified moisture condition under controlled conditions to obtain concrete design strength. The specimens are currently drying in a temperature/humidity controlled environment to achieve the ASTM E 119 prescribed moisture equilibrium.



Figure 2–22. Fabrication of 35 ft span ASTM E 119 test assembly.

#### 2.7.6 WTC 7

The structural response of WTC 7 to damage from debris and fires is being evaluated to identify possible collapse sequences and critical components that are consistent with the videographic and photographic records, interview accounts by individuals that were in or around WTC 7, and other available data.

The analytical work is being conducted with the assistance of Gilsanz Murray Steficek LLP under a contract from NIST and includes the following tasks:

- Task 1. Structural response analysis to identify critical components
- Task 2. Structural analysis of possible collapse initiation hypotheses

The scope of work under Task 1 includes (a) develop a nonlinear global structural model of WTC 7 and evaluate its performance under design gravity loads, (b) identify credible failure sequences for the structural model with service loads and initial structural damage by analyzing the effect of component failures (that may have occurred directly or indirectly from fires) on the structural system stability, (c) identify dominant failure modes for critical components and subsystems determined in (b) for service loads and elevated structural temperatures, (d) conduct parametric studies of critical subsystems to identify influential parameters, and (e) develop approaches to simplify structural analyses for global modeling and analyses.

Selected technical results and finding for progress on Task 1 (a), (b), and (c), data collection of building conditions, working collapse hypotheses, and supporting analyses are presented in the following sections. Appendix L presents more detailed information about the WTC 7 structural design, observations about damage and fires, a timeline and description of the collapse sequence from videographic records, and working collapse hypotheses developed to date. Detailed thermal-structural analyses of selected collapse sequences are planned to refine the working hypotheses presented here and identify probable collapse hypotheses.

## **Summary of Data Collection for Building Conditions**

Data that have been obtained about building conditions from photographic and videographic records and interview accounts include:

- Structural damage to the south face and to the southwest corner from WTC 1 debris was reported by witnesses. A multi-story gash that extended across approximately a quarter to a third of the south face, in the lower portion of the face, was reported by a number of individuals, though details vary. This damage extended to the core area as two elevator cars were reported to be ejected from the elevator shaft at floor 8 or 9. Reported damage to the southwest corner was also seen in photographic records, which show approximately 2 columns and related floor areas missing from floors 8 to 18. Multiple photographic and videographic records also appear to show damage on the south face that started at the roof level and severed the spandrels between exterior columns near the southwest corner for at least 5 to 10 floors. However, the extent and details of this damage have not yet been discerned, as smoke is present.
- The south face was covered by smoke the entire day, following the collapse of WTC 1. This smoke appeared to be emanating from fires in WTC 5, 6, and 7, though the contribution from each building cannot be discerned. The smoke was dense enough that no information about structural damage to the south face has been seen in photographic or videographic records.
- No fires were observed in WTC 7 after WTC 2 collapsed, but fires were observed after WTC 1 collapsed. Fires, or evidence of fires, were observed initially on the south face and near the southwest corner. Many of these fires appeared to burn out before noon to 2 p.m. Around 2 p.m., fires were observed in photographic and videographic records to be burning across floors 11 and 12 on the east face, from the south to the north. Around 3 p.m., fires were observed on floors 7 and 12 along the north face. The fire on floor 12 appeared to bypass the northeast corner and was first observed at a point approximately one third of the width from the northeast corner, and then spread both east and west across the north face. Some time later, fires were observed on floors 8 and 13, with the fire on floor 8 moving from west to east and the fire on floor 13 moving from east to west. At this time, the fire on floor 7 appeared to have stopped progressing near the middle of the north face. The fire on floor 8 continued to move east on the north face, eventually reaching the northeast corner and moving to the east face. Around 4:45 p.m., a photograph showed fires floors 7, 8, 9, and 11 near the middle; floor 12 was burned out by this time.
- Floor 5 did not have any exterior windows, and any fires that may have burned on this floor would not have been visible in photographic or videographic records. However, there was a fuel distribution system on the south, west and north floor areas. Given the variability of damage descriptions for the south face from WTC 1 debris impact, fires on floor 5 will be considered as a possible fire location, subject to further data and/or analysis on building conditions that improve knowledge of fire conditions in this area.
- The first exterior sign of structural failure in WTC 7 was the sinking of the east penthouse roof structure into the building. Photographic and videographic records taken from the north have provided information about the sequence of failure events and their relative times.

Other key observations include window breakage along the east side of the north face, occurring almost simultaneously with the sinking of the east penthouse structure, an approximate 5 s delay before the other roof structures also sink into the building core, a second set of window breakage along the west side of the north face occurring simultaneously with the other roof structure movements, and the appearance of the entire north façade above floor 13 appearing to drop as an intact unit 8 s after the east penthouse movement was first detected.

## **Structural Models and Analysis**

Analyses have been conducted to assess proposed collapse hypotheses that are based upon available information about the building conditions and sequence of events prior to the global collapse. Models and analyses to date have included the following:

- Structural analysis of WTC 7, as built in 1985, for design gravity and wind loads on a global structural model. Development of a reference model for understanding global behavior of the structure, and providing a foundation for other models.
- The global structural model was modified for reported structural damage and estimated service loads for analysis of the structural system response to building condition after debris impact.
- A kinematic structural analysis assisted with identifying possible failure sequences following an initiating event, such as a column or group of columns becoming unstable as steel temperatures reach critical levels.
- Typical tenant floors were analyzed to identify the sequence of floor system load redistribution and component failure for initiating events, such as failure of a support column.
- The global structural model was used to develop a submodel of the lower 10 floors of WTC 7 to evaluate the effect of component failure and load redistribution within this portion of the structural system.
- Thermal-structural analysis of critical columns to fire scenarios for proposed collapse hypotheses have been conducted to evaluate the effect of component response to fires, including time to reach critical uniform elevated temperatures and temperature gradients across component cross-section and length.
- These models were used to consider a range of possible failure scenarios, based upon knowledge of the reported damage, observed or possible fire scenarios, and the exterior failure sequence recorded on videos.

#### **Summary of Technical Results**

Some of the more important technical results developed to date, based upon known building conditions and analyses, include the following:

- The perimeter moment frame was highly redundant and was able to redistribute the loads around the reported damage areas without over-stressing or failing surrounding members.
- The working hypothesis has been developed around four phases of the collapse that were observed in photographic and video records: the initiating event, a vertical progression at the northeast corner of the building, and horizontal progression from the east to west side of the building, and global collapse.
- The first exterior sign of failure in WTC 7 was the displacement at the center of the east penthouse roofline, which appeared to be a kink in the roof line. This kink aligns with columns 79, 80, and 81. This observation has led to postulating initiating event failure sequences that lead to the failure of one of these columns.
- Thermal-structural analyses have been used to evaluate components in postulated initiating event failure sequences. Analyses to date have included single and multi-story columns subject to severe fires (gas temperatures of 1,100 °C), intact and damaged fireproofing, intact and missing lateral support conditions, and temperature-dependent material properties (yield strength, ultimate tensile strength, thermal expansion, and creep strains) to evaluate the structural response to thermal softening, axial expansion, and bowing from thermal gradients. These types of analyses continue to be developed and refined. Simpler initiating events that have been analyzed appear unlikely as initiating events, such as the direct failure of columns 79, 80, or 81 in the lower portion of the building for intact fireproofing and the fires observed in the photographic and videographic records. Other initiating event sequences continue to be postulated and analyzed. Possible initiating events include consideration of interior columns 69, 72, 75, 78, and 78A, the east transfer girder (which supports column 78A and frames into transfer truss #2), and adjacent framing and floor systems and their response to possible structural and fireproofing damage from debris impact and subsequent fire growth and progression. See Appendix L for component locations.
- Interior columns 79, 80, and 81, were located directly below the east penthouse on the roof and supported large tributary areas. The tenant floor areas on the east side of the building had spans of approximately 50 ft between columns. Their failure would likely result in failure of the tributary floor system, as analysis indicates that the floors would not be able to redistribute their loads. This failure mechanism would progress vertically upward within the failed bay to the roof level, and would not be visible from the exterior until the east penthouse lost support, as shown in Fig. 2–23. Available information on the floor-to-column connections indicate that the connections would fail under this scenario without significantly damaging the perimeter or interior columns.




Figure 2–23. Collapse initiation and vertical progression on the east side of WTC 7.

- The debris pile from a vertical failure progression on the east side of the building would damage or sever transfer girders and trusses between the fifth and seventh floors, shown in Fig. 2–24. Two system responses to this secondary damage have been postulated and are being further investigated. (1) The columns supported by these transfer components would become unstable, and their loads would transfer to adjacent core columns. If the columns could not support the transferred loads, the column instability would progress sequentially to adjacent core columns. (2) The floor-to-column connections in the fifth and seventh floors are strong enough to impose lateral displacements upon the other core columns, particularly in the center of core where there were elevator areas without reinforced concrete slab. Such a horizontal pull would fail the columns at their connection near the seventh floor, as shown in Figs. 2–25 and 2–26.
- The core columns failed sequentially and redistributed loads until the building loads could no longer be supported, and the global collapse occurred with few external signs prior to the system failure, as illustrated in Fig. 2–26.

This working hypothesis has been developed to date for the data and analyses described. Continued analyses and evaluation continue toward determining probable collapse sequences.




Figure 2–24. Transfer trusses and girders between the fifth and seventh floors.




Figure 2–25. Example of horizontal progression of failure in core columns following damage to transfer components on the east side of the building.




Figure 2–26. Horizontal progression to the west side of WTC 7.

# 2.8 OCCUPANT BEHAVIOR, EGRESS, AND EMERGENCY COMMUNICATIONS (PROJECT 7)

The purpose of this project is to determine the behavior and fate of occupants and responders - both those who survived and those who did not - by collecting and analyzing information on occupant behavior, human factors, egress, and emergency communications in WTC 1, 2, and 7, and evaluating the performance of the evacuation system on September 11, 2001.

#### 2.8.1 Project Objectives

This project is divided into six tasks as follows:

• Task 1. Gather baseline information on the evacuation of the WTC buildings on September 11, 2001 through a comprehensive, systems-oriented, and interdisciplinary data collection effort focused on occupant behavior, human factors, egress, and emergency communications (including instructions given, interpretation of instructions, and response to instructions). This involves the collection of new data from people affected by the WTC attacks (e.g., building occupants, building operators, and first responders via direct accounts from survivors and families of victims), especially those who had to evacuate the buildings. Experts in human behavior and statistical sampling were used develop a data acquisition strategy that considers various data collection methods such as interviews and questionnaires. Inputs and suggestions were obtained from organizations with an interest in the content of the data collection effort. Additionally, written accounts, transcripts of (emergency)

- communications, published accounts, and other sources of egress related information were obtained, in coordination with other data collection efforts for the investigation.
- Task 2. Collect archival records from prior WTC evacuation incidents (e.g., 1975 fire, 1977 blackout, 1980 bomb scare, 1990 power outage, and 1993 bombing) and practice evacuations, including oral history data from floor wardens and fire safety directors. These records are compared and contrasted with the September 11, 2001, incident evacuation. Changes made to the evacuation procedures following the earlier incidents and in recent years will be evaluated in the context of the experience on September 11, 2001.
- Task 3. Document pre-event data for WTC Buildings 1, 2, and 7. This information includes, but is not limited to, physical aspects of building egress components, such as stairs (width, number, location, vertical continuity), evacuation lighting, back-up power, elevators (number, operational before and after impact, role in evacuation), and active fire protection systems (sprinklers, manual suppression, fire alarms, smoke control). Building plans, emergency plans, type and frequency of evacuation drills, occupancy level and distribution on the morning of September 11, 2001, and communications also constitute pre-event data. This information provides a baseline for evaluating the performance of the egress system.
- Task 4. Store the information collected in Task 1 in a database. Additionally, information from third-party sources, such as television interviews and newspaper articles, as well as other relevant published material, will be analyzed, examined, and assembled in the database.
- Task 5. Analyze the data to study the movement of people during the evacuations, decision-making and situation awareness, and issues concerning persons with disabilities. A timeline of the evacuation will be developed using the results of these analyses together with other data sources. This timeline will be compared with the timeline of the structural response, the development of the interior conditions (fire and smoke), as well as activation of the active fire protection systems. The characteristics of the WTC evacuation designs and protocols will be evaluated, including the performance of stairs and elevators, emergency communications, and the temperature and smoke conditions. The designs will also be compared with building code requirements and practices for tall buildings in other major cities worldwide. The observed evacuation data will be compared with results obtained using alternate egress models to better understand occupant behavior and identify needed improvements to existing egress models. In addition, the evacuation experience will be compared with previous evacuation incidents in these buildings. The results of the analyses will be reviewed in the context of occupant protection practices for tall buildings, including the consideration of full evacuation and phased evacuation strategies.
- Task 6. Report preparation. The results of this project will be synthesized into a chapter to describe the occupant behavior, egress, and emergency communications in WTC 1, 2, and 7, and the performance of the evacuation system. The project staff will contribute to drafting the final investigation report for review by the National Construction Safety Team (NCST) Advisory Committee.

# 2.8.2 Project Status

Project 7 has made significant progress since the last interim report. Data collection is substantially complete, including interviews and focus groups with survivors and family members. Significant portions of the data analysis are complete, and egress modeling is under way.

#### Face-to-Face Interviews, Telephone Interviews, and Focus Groups

Over 220 face-to-face interviews have been completed with occupants of WTC 1, 2, and 7, and family members of victims. These numbers do not reflect interviews conducted with first responders or other key building personnel. A preliminary analysis of the interview data indicates that the topic areas of interest and physical building locations of the occupants have resulted in an adequate number of interviews to support analysis. While additional face-to-face interviews may occur in the near future should conditions necessitate, no further interviews are scheduled. Face-to-face interviews typically required two hours, with some requiring significantly more or less depending upon the particular experiences of the respondent. Data were collected using a cooperative, electronic format, previously described as the cue-action-reason technique. The technique formalized a logical, chronological data collection, enabling detailed recall, and diminishing gaps in continuity of actions.

# **Egress Simulation**

The purpose of the modeling project is to obtain evacuation times for two different evacuation procedures for the WTC towers, phased evacuation and total evacuation of the occupants from the buildings. The first objective is to simulate a phased evacuation of WTC 1 or WTC 2, which involves the evacuation of the occupants on the fire floor, the floor above, and the floor below to a specific floor of the building. For this simulation, a representative fire floor was chosen within one of the towers, and the simulation consisted of occupants from the fire floor, the floor below, and the floor above evacuated to two floors below the fire floor. The purpose of the phased evacuation simulation is to obtain evacuation results (time) on how the evacuation from a fire emergency was supposed to work.

The second objective is to simulate total evacuation of the building, and involves three different scenarios. The first total evacuation scenario is the simulation of a full capacity building evacuation (without damage) involving all occupied floors of a WTC tower. The second scenario involves a full capacity building evacuation of WTC 1 with plane damage blocking floors 91 to 110 and a full capacity building evacuation of WTC 2 with plane damage blocking floors 78 to 110. The second scenario will be used to show how long it would have taken occupants in a scenario resembling the September 11, 2001, emergency to evacuate if each tower was fully occupied. Finally, the third scenario is a simulation of a September 11, 2001, capacity building evacuation from a WTC tower. The results from the simulation of the third full evacuation scenario will be compared with evacuation time results obtained from the telephone interviews in an attempt to verify the accuracy of the model. None of the simulations run for this project involves the simulation of the fire environment.

Three evacuation models will be used to perform the modeling objectives outlined in the previous paragraphs. These models are Simulex (IES 2000 and IES 2001), EXIT89 (Fahy 1999), and buildingEXODUS (Galea et al. 2001). Simulex will be used in a limited capacity to simulate the phased

evacuation and observe occupant movement on specific floors. EXIT89 and buildingEXODUS will be used in all of the objectives stated above.

#### Other September 11, 2001, Data Collection

A systematic review of all 9-1-1 emergency calls related to the WTC attacks between 8:46 a.m. and 10:28 a.m. was completed. Occupants from inside the WTC called 9-1-1, sometimes repeatedly, in order to report where they were trapped, the conditions on the floor, and how many other people they were with. The callers often requested advice, guidance, information about the attack, and the progress of the rescue efforts. The information relayed to the 9-1-1 system was unique and invaluable in specificity and timing. Information related to building damage, fire and smoke spread, and occupant mobility has been integrated with other aspects of the NIST investigation.

Seven-hundred forty-five media accounts from were compiled and analyzed. Finally, information about significant previous building fires and evacuations has been compiled as background. An overview of the preliminary results of both analyses is included in the next section, while more detailed analyses are contained in Appendix N and Appendix O. The database can be obtained electronically at http://wtc.nist.gov.

Collection of documents related to the design and maintenance of the egress and emergency communication systems is complete. This collection was coordinated with Project 1, Analysis of Codes, Standards, and Practices.

## **Data Analysis**

Every data channel is being analyzed and synthesized to form a complete understanding of the evacuation of WTC 1, 2, and 7 on September 11, 2001. There are two primary analysis modes, proceeding in parallel: quantitative and qualitative. Quantitative analysis techniques are being implemented with the telephone interview data. An example of the quantitative data analysis can be found in Appendix N. The SPSS 12.0 data analysis package is being used to analyze the telephone interview data. The qualitative analysis is being consolidated with the ATLAS.ti 4.2 program. All face-to-face interviews, 9-1-1 emergency call records, focus group notes, emergency communications, and formal complaints will be simultaneously analyzed using over 100 coding variables. The coding variables encompass the entire scope of Project 7 objectives and are coordinated with the analyses conducted by other projects within the investigation, particularly Project 8, First Responder Technologies and Guidelines.

#### 2.8.3 Interim Findings and Key Issues

#### **Significant Historical Building Incidents**

Although historically the WTC attack, subsequent fires, and building collapses are arguably the most significant fire event where building egress played a critical role, concern for fires in large buildings is hardly new. In many cases, provisions in current building codes evolved as a result of high-rise fires as early as 1911 where egress or collapse was an important issue. These provisions include remoteness and protection of egress stairways, the need for control of combustible contents of buildings, the need to

provide sprinklers or other alternatives for high-rise buildings, and concern that sprayed-on fireproofing may not adhere properly to surfaces or may be dislodged.

#### **Analysis of Published Accounts**

NIST contracted with the NFPA to collect first-person accounts from newspapers, radio and television programs, e-mail exchanges, and a variety of websites. Over a period of 18 months, a total of 745 first-person accounts were collected. These accounts had been published up to 14 months after the event. Although media accounts do not provide the scientific rigor of a proper study, they do present important insights into the events of the day. The objectives of the analysis of the first-person accounts were to gain insight into the variability of human behavior and response time displayed during the evacuation, with the findings to be used as a guide for additional investigation. It should be acknowledged that content analysis of first-person accounts has important limitations: the questions asked by journalists are usually unknown, and, some details might be left unreported and the most dramatic stories over represented. Consequently, the results cannot be generalized to the overall population of the WTC towers.

To analyze the content of the first-person accounts, a questionnaire tool was developed and used to "interview" each account. The questionnaire had 33 questions such as: "On what floor was the person?," "What was the first cue of the event?," "Was the person injured?," or "What were the conditions in the stairs?" Not every account provided answers for all 33 questions, since some accounts lacked certain details, but this is similar to a respondent who did not answer some questions in a survey. Once the 745 first-person accounts were summarized, multiple accounts from the same person were merged into one, which provided accounts for 465 individuals. (Some survivors provided multiple accounts through different sources.) Before any analysis began, the database was further limited to the 435 civilian building occupants who were in either WTC 1 or WTC 2 on that day.

In summary, the accounts analyzed were from 435 individuals; 251 occupants of WTC 1 and 184 occupants of WTC 2. They represented the three different floor strata of the two towers. The accounts were mainly from men (314 versus 118) and from people varying in age from 20 to 89 years old. Among the interesting results found was the means of egress used that morning. Out of 158 people who mentioned their means of egress in WTC 2, 18 used the elevators, and 26 used a combination of stairs and elevators to leave the tower. It was found that the higher the person was located in the tower initially, the more likely it was that this person used an elevator to evacuate. In WTC 1, out of 202 people who mentioned their means of egress, 198 used the stairs, 1 used an elevator, and 3 used a combination of stairs and elevator. This does not include the 22 people who were stuck in elevators when WTC 1 was hit. The most common adverse floor condition mentioned by people in WTC 1 was the presence of smoke (mentioned by 74 people), debris or collapsed walls, ceilings, or floors (72 people), and fires (41 people). In WTC 2, 37 people reported debris or collapsed walls, ceilings or floors on their floor, and 25 people saw smoke.

The most prevalent condition reported for the stairwell was that it was crowded and hot (mentioned by 106 people). A particular condition mentioned for the stairs in both towers was the presence of smoke, mentioned by 78 people in WTC 1 and 29 in WTC 2. The presence of water, usually on the lower stairwell floors, was mentioned by 49 people in WTC 1 and four people in WTC 2. Jammed or locked doors were mentioned by 20 people in WTC 1 and two people in WTC 2.

In WTC 2, 96 people mentioned hearing a message over the communication system to "stay in or return to their office." The majority of them, 69 people, decided to disregard the instructions and continued their evacuation. The 16 people who decided to remain in their offices or decided to turn back didn't have time to travel very far before the second plane hit; at that point they all resumed their evacuation downward.

Among the accounts analyzed, 27 people reported having a disability, and 47 were injured that morning. All these people were supported in their evacuation by coworkers. Half of them stated that they started their evacuation immediately, and one-third mentioned some delay to get organized and seek first-aid. Several people who were disabled or injured evacuated the towers swiftly as occupants formed a single line to let them through rapidly down the stairwell. Many people (143 in WTC 1 and 26 in WTC 2) mentioned being reassured and feeling safe when meeting firefighters in the building. Although the emergency crews disrupted the evacuation in the stairwell by going against traffic, the people appreciatively cheered them on. Phone calls were made by 151 survivors to family and friends to give and obtain information; 20 people called their bosses or colleagues; and another 12 people made calls to authorities. Another 14 people used e-mail wireless technology and pagers to exchange information, which seems to be the only reliable devices used from inside the stairwells.

#### **Telephone Interviews**

The survey objectives of the telephone interviews called for collecting 800 computer-assisted telephone interviews (CATI) of persons occupying either of the two WTC towers at the time of the terrorist attacks on September 11, 2001. Attempts were made to equally divide the respondents among WTC 1 and WTC 2 occupants (i.e., n = 400 occupant interviews from each tower). Within each of the WTC buildings, independent, proportionate, stratified samples of survivors were drawn. Eight-hundred three telephone interviews were completed, with 440 from WTC 1 and 363 from WTC 2. Additional discussion of the sampling methodology and disposition can be found in Appendix O.

A response rate analysis indicated differential nonresponse, more noticeably near the impact floors in WTC 1. In other words, respondents were less likely to complete a telephone interview if they had been near the impact floor than respondents who had been lower in the building. Thus, percentages presented in this summary are weighted, unless otherwise indicated. Weighting preserves the ability to accurately generalize the results.

#### Population of WTC 1 and WTC 2 on September 11, 2001

The total building population is the sum of survivors and decedents. At the time of this report, the City of New York has officially determined that 2,749 people were killed at the WTC on September 11, 2001; no official breakdown of where people were killed presently exists. While an analysis of this issue by Dennis Cauchon, a reporter for *USA Today*, in the months immediately following September 11, 2001, was remarkably complete (Cauchon 2001), differences exist between his projections and the official numbers from the City of New York and other official sources. These differences are shown in Table 2–8. For example, the number of first responders depends on the definition of first responder. The City of New York published an occupational analysis of WTC decedents based on a Census of Fatal Occupational Injuries (U.S. Department of Labor, Bureau of Labor Statistics, in cooperation with the NYC Department of Health and Mental Hygiene and State and Federal agencies). Four hundred and thirty-three decedents' occupations were listed as firefighting, police, or security. This number exceeds

by 30 the number of FDNY, NYPD, and PAPD reported killed. This may be attributable to private security forces present inside the towers on September 11 and/or first responders not employed by New York City or PANYNJ. NIST is attempting to resolve these differences in order to fully understand the initial building population.

Table 2–8. Reports of WTC decedents.

Decedent		fficial ımbers	USA Today <sup>a</sup>
WTC 1 occupants			1,434
At or above impact			1,360
Below impact			72
WTC 2 occupants			599
At or above impact			595
Below impact			4
First responders (total)	4	133 <sup>b,c</sup>	479
FDNY		343 <sup>e</sup>	
NYPD	403 <sup>d</sup>	23 <sup>f</sup>	
PAPD	7	37 <sup>g</sup>	
UA 175 and AA 11		157 <sup>d</sup>	157
Uncertain location in towers			147
Bystanders			10
Total number of decedents	2,749 <sup>b,h</sup>		2,826

- Cauchon, Dennis. 'For many on September, 11, 2001, survival was no accident.' USA Today, December 20, 2001.
- Summary of Vital Statistics 2002: The City of New York. Bureau of Vital Statistics, NYC Department of Health and Mental Hygiene. December 2003.
- Table WTC 8: Occupation of Decedents. All decedents classified as 'protective service' occupations, which includes firefighting, police, and guards.
- d. World Trade Center Building Performance Study. FEMA 403. May 2002. Includes 10 hijackers as passengers.
- Increasing FDNY's Preparedness (McKinsey Report). Available at: http://www.ci.nyc.ny.us/html/fdny/html/mck report/index.shtml
- f. Available at http://www.ci.nyc.ny.us/html/nypd/html/memorial\_ 01.html
- g. Available at http://www.panynj.gov/AboutthePortAuthority/ PortAuthorityPolice/InMemorium/
- h. Does not include 10 airplane hijackers for whom the City has not issued death certificates.

Using the known eligibility rates allows for a projection of the survivors of WTC 1 and WTC 2 present in the building at 8:46 a.m. on September 11, 2001. The analysis indicates that WTC 1 had approximately  $7,500 \pm 750$  surviving occupants, while WTC 2 had approximately  $7,900 \pm 900$  surviving occupants. Thus, the total population of survivors from both towers was  $15,400 \pm 1,200$ . Table 2–9 summarizes the projection of population of WTC 1 and WTC 2 on September 11, 2001. Pending resolution of decedent locations, the total building population at the time of the first airplane impact was  $17,400 \pm 1,200$ , calculated using the building decedent locations reported by Cauchon.

Table 2–9. Occupancy estimates on September 11, 2001, by tower.

·	WTC 1	WTC 2	Total		
Estimated total population of survivors	7,500	7,900	15,400		
Statistical Precision Calculations					
Sample n	427	376	803		
Standard error (p)	1.90 %	1.92 %	1.36 %		
Standard error (total)	750	900	1,200		
Confidence limits at 5%	±1,470	±1,790	±2,320		
Number of Occupant Decedents					
Decedents	1,434 <sup>a</sup>	599ª	$2,033^a - 2,236^b$		
Total Building Population					
Total population	8,900	8,500	17,400		

a. Calculated as 2,749 – 343 FDNY – 23 NYPD – 147 airplane passengers (not including hijackers).

#### **Previous Evacuation Experience**

Whether an occupant had a previous evacuation experience may have affected the decisions an individual made during the September 11, 2001, evacuation. NIST will conduct further analysis to develop this hypothesis. Of the WTC 1 occupants present on September 11, 2001, 16 percent (n = 64) were also present during the 1993 bombing. Sixty percent (n = 38) of WTC 1 evacuees in 1993 reported that they evacuated immediately, 30 percent (n = 20) reported that they waited to evacuate, and 9 percent (n = 6) did not recall. Most (95 percent [n = 53]) who were able to recall their evacuation decision felt that they made the right decision, while 5 percent (n = 3) did not believe they made the right decision.

Similarly, 16 percent (n = 59) of WTC 2 evacuees on September 11, 2001, also evacuated in 1993. In WTC 2, however, only 75 percent (n = 42) felt that they made the right decision in 1993, possibly due to the fact that many more waited to evacuate in 1993 in WTC 2 (69 percent [n = 39]) than did so in WTC 1. Only 31 percent (n = 17) who reported their decision evacuated immediately from WTC 2 in 1993, keeping in mind that the bomb had a more significant impact on WTC 1 in 1993.

#### **Preparedness and Training**

Long a cornerstone of public policy on the emergency preparedness of office workers around the country, the Port Authority required tenants to conduct fire drills every 6 months and appoint employee floor wardens and searchers. Sixty-six percent (n = 529) of WTC 1 and WTC 2 occupants reported participation in at least one fire drill in the 12 months immediately prior to September 11, 2001. Seventeen percent (n = 139) reported that they did not participate in any fire drills in the 12 months prior to September 11, and 17 percent (n = 135) did not know. Fire drill participation rates were similar between the two towers (as shown in Table 2–10).

b. Calculated as 2,749 – 403 First Responders – 157 airline passengers (not including hijackers).

Table 2–10. WTC fire drills in 12 months prior to September 11, 2001.<sup>a</sup>

Number of Drills	WTC 1	WTC 2
None	18 % (n = 78)	17 % (n = 61)
1	13 % (n = 57)	8 % (n = 29)
2	21 % (n = 90)	24 % (n = 88)
3	11 % (n = 47)	15 % (n = 53)
4	10 % (n = 44)	9 % (n = 32)
5–11	7 % (n = 31)	9 % (n = 32)
12 or more	3 % (n = 13)	4 % (n = 13)
Unknown	18 % (n = 80)	15 % (n = 55)

a. Percentages are weighted, n values unweighted.

One of the primary goals of fire drill training is to make occupants aware of the location of the emergency exits. Ninety-three percent (n = 490) of respondents who reported participation in a fire drill were instructed about the location of the nearest stairwell as part of the drill. However, of the respondents who reported being shown a stairwell, 82 percent (n = 432) did not enter or use the stairwell. Seventeen percent (n = 92) reported that they did use the stairs during a drill, while approximately 1 percent (n = 5) reported not knowing. Overall, more than half (51 percent [n = 415]) of the occupants had never used a stairwell in WTC 1 or WTC 2 prior to September 11, while 48 percent (n = 386) had used a stairwell. Two persons reported not knowing whether they had used the stairs previously.

Another goal of the fire drills was to introduce the floor warden system and evacuation procedures. Eighty-two percent (n = 528) of the occupants with fire drill training were aware that there was a floor warden for their floor. Approximately 70 percent (n = 557) of all occupants reported that they were aware of the evacuation procedures. When asked what those evacuation procedures comprised, however, answers varied significantly, including: wait in hallway for further instructions; do not use elevators, use stairs; meet at a designated site outside the building for a head count; or proceed down (varied number of) flights of stairs and wait. Further analysis of the understanding and implementation of the emergency procedures is under way.

#### **Future Work**

Significant additional analysis is presently under way. It is particularly important that results of questions related to the events, observations, and activities within the towers on September 11, 2001, be analyzed within the context of the findings coming from face-to-face interviews, focus groups, and other data collection activities. As with the work presented in this appendix, ongoing analysis of the telephone interviews will form the statistical basis for many significant recommendations, and there will be continued analysis of the information collected during the face-to-face interviews and focus groups.

NIST is utilizing existing computer egress models to better understand the evacuation experience on September 11, 2001. Three full evacuation scenarios are being considered: a typical full capacity building evacuation assuming the WTC tower is fully occupied—with one case considering only tenants and another case considering both tenants and visitors; a full capacity building evacuation of each WTC

tower with aircraft impact damage; and a September 11, 2001, capacity evacuation from a WTC tower. NIST is using two classes of egress models in order to frame the evacuation questions: (1) partial behavior: simulates occupant movement and limited behavioral rules by including delay times, smoke effects, and occupant characteristics; and (2) behavioral: simulates movement and more comprehensive evacuation decisions and activities.

# 2.9 FIRE SERVICE TECHNOLOGIES AND GUIDELINES (PROJECT 8)

The purpose of this project is to build on work already done by the FDNY and McKinsey & Company by (1) fully documenting what happened during the response by the fire services to the attacks on the WTC up to the time of collapse of WTC 7; (2) identifying issues that need to be addressed in changes to practices, standards, and codes; (3) identifying alternative practices and/or technologies that may address these issues; and (4) identifying research and development (R&D) needs that advance the safety of the fire service in responding to massive fires in tall buildings.

#### 2.9.1 Project Objectives

Project 8, Fire Service Technologies and Guidelines, has four tasks:

- Task 1. Collect emergency response data in cooperation with FDNY to document first responder fatalities, command and control procedures, and equipment performance. Records of interest include dispatch logs, recorded radio communications, run logs from surviving responding units, 9-1-1 records, data recorded by the FDNY, PANYNJ operations, and the NYPD, and fireground positioning of emergency apparatus. Information will also be sought on operations and function of communications systems, on-site emergency information systems, fire alarm panels, elevator control panels, standpipes and fire hoses, and other prepositioned emergency equipment. In coordination with Project 7, Occupant Behavior, Egress, and Emergency Communications, oral history data will be collected from witnesses, those in control of emergency operations, and surviving first responders to the extent their oral history has not already been documented. Technical experts will review and conduct a fact-based analysis of the data.
- Task 2. Interpret the factual analysis to determine the effect on responder successes of factors such as:
  - The influence of building design (e.g., height, stairways, elevators, smoke control systems) on fire service command and control procedures, life saving operations, and safety of rescue personnel;
  - The influence of aircraft impact damage and fuel run-off on fire service command and control procedures, life saving operations, and safety of rescue personnel;
  - The impact of systems failures (e.g., communications systems, water supply, sprinklers, standpipes) on fire service command and control procedures, life saving operations, and safety of rescue personnel;

- Building occupant egress as related to fire service operations;
- The ability to fight large fires on the upper floors of tall buildings;
- The impact that the 1993 bombing of the WTC had on codes, standards, and procedures that affected first responders in tall buildings;
- Preplanning, training, and standard operating procedures (including command and control) at the time of the incident;
- Firefighter accountability, location, and tracking;
- Fire and emergency response protocols for tall buildings;
- The resources available for initial situation assessment and incident management, and practices for determining the possibility of structural collapse; and
- Communications and coordination of response activities with other authorities at the incident.
- Task 3. Identify alternative emergency response practices and technologies that may advance the safety and effectiveness of first responders, such as: knowledge/information systems for command and control decisions; elevator use by firefighters; firefighter tracking systems; interoperability of communication systems (occupants, firefighters, police, emergency management services); fire growth and smoke hazard prediction; structural safety monitoring, assessment and prediction; and simulation tools for training.
- Task 4. Report preparation. The results of this project will be synthesized into a report to describe the actions of the fire service and performance of their equipment; identify available alternatives related to fire service technology, training, and operational procedures; and identify R&D needs in support of their capability to protect the public, themselves, and vital physical infrastructure during extreme events.

## 2.9.2 Project Status

#### Task 1, Data Collection

Project 8 has collected or reviewed a large volume of data from the three primary departments that sent first responders to the WTC, FDNY, NYPD, and PANYNJ. NYC submitted data directly to NIST for analysis and also provided NIST with the opportunity to review other data related to the incident in their offices. The data collection and review process is largely completed. Data collected and review includes: documentary data, electronic data, and first-person face-to-face interviews.

Documentary data collected or reviewed included the following:

- Official lists of first responder fatalities
- FDNY and NYPD McKinsey & Company reports

- FDNY dispatch logs
- FDNY run logs of surviving units (CD12/CD15)
- FDNY standard operating procedures and policies
- Documents describing radio communications equipment and operations
- Review of approximately 500 interviews conducted by FDNY

The following electronic data have been collected or reviewed:

- Approximately 1,000 hours of radio and telephone communications for PAPD and other departments within the Port Authority
- NYPD Special Operations Division and Division 1 tape recordings
- NYC 9-1-1 Emergency Telephone Operator tapes
- FDNY Fire Dispatcher tapes

First-person interviews—To date, 108 face-to-face emergency responder interviews have been completed:

- 68 FDNY personnel including Commissioners, Chief Officers, Company Officers, Firefighters, and Emergency Medical Service personnel
- 24 NYPD personnel including Commissioners, Chief Officers, Aviation Officers, Emergency Service Unit personnel, and Police Officers
- 13 PANYNJ personnel including managers, directors, communications personnel, vertical transportation personnel, fire safety personnel, security personnel, PAPD Chief Officers, and Police Officers
- 3 other emergency responders including security personnel, fire safety personnel, and communications personnel

#### Task 2, Factual Analysis of the Collected Data

As documentary data were collected they were reviewed for information critical to understanding the emergency response at the WTC. This information has been filed relative to the source of information and the type of information. The documentary data are being compared with other data gained through communications records and recordings and first-person face-to-face interviews. The data are in the process of being coded for analysis using Atlas.ti software.

In addition, Appendix P contains results from a preliminary analysis of emergency responder communications. The objective of this analysis is to develop a better understanding of the role that emergency communications played during the WTC attack, and to quantify information related to communications effectiveness. Although there have been numerous reports of radio equipment failures

during the emergency response at the WTC, and these are all being examined as part of the overall project, the only radio equipment system examined in this preliminary report is that of the FDNY WTC site high-rise repeater that was installed by the Port Authority. Many factors are associated with the ability of emergency communications to be successful. The following objectives were set in this report:

- To document radio and telephone communications operations
- To document radio communications readability or understandability
- To quantify radio communications traffic volume
- To understand the impact of traffic volume on communications readability and the transfer of information
- To identify communications associated with dispatch and arrival of responders
- To identify communications related to evacuation and emergency response operations
- To identify communications related to building conditions at the WTC and the impact of this information on the emergency response.

Results from this analysis are presented in Sections 2.9.3, Preliminary Results on Emergency Responder Communications; 2.9.4, Preliminary Findings; and Appendix P, Interim Report on Emergency Communications.

Appendix P also contains a detailed description of methods used for documenting and analyzing the communications data obtained from the various sources.

## Task 3, Alternative Emergency Response Practices and Technologies

As the data analysis has progressed, issues critical to emergency responder operations are being identified. Most of the critical practices and technologies identified relate to Command and Control, Communications, and significant issues related to emergency responder high-rise building operations. This work is still in progress, and details concerning alternative practices and technologies will be addressed in the final report.

#### Task 4, Report Preparation

The efforts described above in Tasks 1, 2, and 3 continue. Data analysis necessary for final report preparations is ongoing. The final report outline has been drafted, and report preparation has been initiated.

#### 2.9.3 Preliminary Results on Emergency Responder Communications

A more detailed analysis of radio equipment and systems operations is in progress, and it will be addressed in the final report. However, the following preliminary results on emergency communications

provide some insight into the challenges associated with communications systems following the attack on the WTC.

All radio systems analyzed appeared to work well during the normal operations period just before the attack on the WTC. It was noted that Channel W of the PAPD was experiencing some difficulty with a handie-talkie radio transmitting a carrier wave from an open or keyed microphone. This disrupted communications on that channel. PAPD personnel were trying to correct the problem just before the first aircraft struck WTC 1. The problem continued after the attack occurred. NYPD also had a problem with an open microphone after the incident began. This occurred on the Special Operations Division (SOD) channel. Efforts made by NYPD personnel corrected the problem.

All radio communications evaluated experienced traffic volume surge load conditions as a result of the attack. Coupled with the increase of traffic load was a significant increase in a process known as "Doubling" or "Crossing" of radio signals. This condition occurs when more that one person attempts to transmit a message at the same time on the same radio frequency. Doubling results in the mixing of radio signals that seriously degrades the signal readability. This condition will often block all clear communications from getting through, except possibly from a high power base station.

## 2.9.4 Preliminary Findings

The following are preliminary findings based on the current status of emergency responder communications analysis:

- After the first aircraft struck WTC 1, there was an approximate factor of 5 peak increase in traffic level over the normal level of emergency responder radio communications, followed by an approximate factor of 3 steady increase in the level of subsequent traffic.
- A surge in communications traffic volume made it more difficult to handle the flow of communications and delivery of information.
- Analysis of the radio communications records received by NIST indicates that roughly onethird to one-half of the radio messages transmitted during these radio traffic surge conditions were not complete messages nor understandable.
- Preliminary analysis of the FDNY City-wide, high-rise Channel 7 (PAPD Channel 30) recording indicates that the WTC site repeater was operating.
- Communications records and interviews indicate that smoke and heat conditions on the top of the two WTC buildings prevented the NYPD helicopters from conducting safe roof evacuation operations.
- NYPD aviation unit personnel reported critical information about the impending collapse of
  the WTC towers several minutes prior to their collapse. No evidence has been found to
  suggest that the information was further communicated to all emergency responders at the
  scene.

Analysis of communications records and face-to-face interviews with emergency responders indicate that radio and telephone communications were a critical part of the emergency response operations. It is also clear from the evaluation that communications technology was not operating at a performance level adequate for handling emergency responder requirements at the incident.

#### 2.10 REFERENCES

- ASME (American Society of Mechanical Engineers). 2000. Safety Code for Elevators and Escalators, ASME 17.1, New York, NY.
- ASTM (ASTM International). 2003. Test Methods for Fire Tests of Building Construction and Materials, ASTM E 119-00a, 2003 Annual Book of ASTM Standards, Vol. 04.07, West Conshohocken, PA.
- Bell and Stanton, Public Relations. 1964. Polytechnic Institute of Brooklyn, 757 Third Ave, New York, NY.
- BOCA (Building Officials Conference of America). 1950. Basic Building Code, 1950 Edition, New York, NY.
- BOCA (Building Officials Conference of America). 1965. Basic Building Code, Fourth Edition, Building Officials Conference of America, Chicago, IL.
- Bracco, W.M. (Tishman Research Corporation). 1969. Office Correspondence to James R. Endler (Vice President, Tishman Realty & Construction Co.), May 26.
- Cauchon, Dennis. 2001. For Many on Sept.11, Survival Was No Accident, USA Today, December 20.
- Coty, Eric H. (Rolf Jensen and Associates, Inc.). 1997. Included as Attachment A to World Trade Center Code Compliance Evaluation compiled by PANYNJ October 15, 1999, March 14.
- Endler, James R. (Vice President, Tishman Realty & Construction Co., Inc.). 1969. Letter to Malcolm P. Levy (General Manager, World Trade Center Operations), July 9.
- Fahy, R.F. 1999. User's Manual, EXIT89 v 1.01, An Evacuation Model for High-Rise Buildings, National Fire Protection Association, Quincy, MA., December.
- Feld, Lester S. (Chief Structural Engineer, World Trade Department). 1987. Memorandum to Robert J. Linn (Deputy Director for Physical Facilities, World Trade Department), January 15.
- Galea, E.R., S. Gwynne, P.J. Lawrence, L. Fillippidis, and D. Blackshields. 2001. building EXODUS V3.01 User Guide and Technical Manual, Revision 3.0, University of Greenwich, London, UK, February.
- ICBO (International Conference of Building Officials). 1928. Uniform Building Code 1927 Edition, Long Beach, CA.
- ICC (International Code Council). 2000. International Building Code, IBC 2000, Falls Church, VA.

- ICC (International Code Council). 2003. International Building Code, IBC 2003, Falls Church, VA.
- IES (Integrated Environmental Solutions, Inc.). 2000. Simulex Technical Reference, Evacuation Modeling Software, November.
- IES (Integrated Environmental Solutions, Inc.). 2001. Simulex User Manual, Evacuation Modeling Software, March.
- Kyle, John M. (Chief Engineer, Port Authority). 1966. Memorandum to Guy F. Tozzoli (Director, World Trade Department), June 2.
- Levy, Malcolm. 1963. Port of New York Authority Letter to Minoru Yamasaki (Architect, Minoru Yamasaki & Associates), May 15.
- Levy, Malcolm. 1965. Port of New York Authority Letter to Minoru Yamasaki (Architect, Minoru Yamasaki & Associates), September 29.
- MCC (Municipal Code of Chicago). 1967. Municipal Code of Chicago Relating to Buildings (As amended to and including January 1, 1967), Index Publishing Corp., Chicago, IL.
- Messersmith, J.J. 2002. Unwarranted Relaxation, *Concrete Products*, Sept. 1. http://concreteproducts.com/mag/concrete\_unwarranted\_relaxation/index.html
- NBFU (National Board of Fire Underwriters). 1934. National Building Code, Fifth Edition, Revised Reprint of 1931 Edition, New York, NY.
- NFPA (National Fire Protection Association). 1966. Life Safety Code, NFPA 101, Quincy, Massachusetts
- NFPA (National Fire Protection Association). 2003. Building Construction and Safety Code, NFPA 5000, Quincy, MA.
- NYCBC 1968. Building Code—Local Law No. 76 of the City of New York, New York, NY.
- NYCBC 2001. Building Code of the City of New York, 2001 Edition, Gould Publications, Binghamton, NY.
- NYSBC 1964. State Building Construction Code Applicable to General Building Construction, Building Code Bureau, State of New York, New York, NY, December 1.
- PANYNJ (Port Authority of New York and New Jersey). 1998. World Trade Center Design Guidelines, Specifications, and Standard Details, February 27, revised May 11.
- PANYNJ (Port Authority of New York and New Jersey). 1999. World Trade Center Code Compliance Evaluation, October 15.
- PANYNJ and FDNY. 1993. Memorandum of Understanding Between the Fire Department of the City of New York and the Port Authority of New York and New Jersey, signed by Stanley Brezenhoff, Executive Director, PANYNJ, and William Feehan, Fire Commissioner, FDNY, December 30.

- PANYNJ and NYCDOB. 1993. Memorandum of Understanding between the Port Authority of New York & New Jersey and New York City Department of Buildings, signed by Stanley Brezenhoff, Executive Director, PANYNJ, November 3, and Stewart D. O'Brien, Acting Commissioner, NYCDOB, October 28.
- PANYNJ and NYCDOB. 1995. Supplement to Memorandum of Understanding Between the New York City Department of Buildings and the Port Authority of New York and New Jersey, signed June 1 and 7, 1995, with change dated September 15.
- PONYA (Port of New York Authority). 1976. Report on Fire Safety of the World Trade Center, January.
- Powers, W. Robert (New York Board of Fire Underwriters). 1975. One World Trade Center Fire, Bureau of Fire Prevention and Public Relations, New York, NY, February 13.
- Rivera, Carlos M. and Rudolf J. Rinaldi. 1993, Fire and Building Codes and the Jurisdiction and Compliance of Federal, State, State Authorities and Foreign Government Buildings, March 25.
- SBCC (Southern Building Code Congress). 1946. Southern Standard Building Code, 1946-47 Edition, Birmingham, AL.
- Schaffner, Charles E. 1964. The new building code for New York City—Performance or specification, *The Magazine of Standards*, October.
- Solomon, Joseph H. (Emery Roth & Sons). 1969. Letter to Malcolm P. Levy (Chief, WTC Planning Division Port Authority), June 6.
- Solomon, Joseph H. (Emery Roth & Sons). 1975. Letter to Malcolm P. Levy (General Manager, World Trade Center Operations), February 18.

This page intentionally left blank.